

. .& .

3

μ

μ

2

μ

2012

001	15.643441
002	17.205541
003	20.290479
026	.099900
036	.090700
273	1.084300
297.1	1.910000
510	3.020000
511	.620000
513	1.200000
561	2.030000
565.3	3.800000
566.3	5.050000
567.13	19.210000
571.5.1	2.670000
572.1.7	3.380000
575.3	
581.2	9.090000
582.2	27.000000
588.3	
603.3	5.650000
605.3.5	136.000000
619.2.2	44.600000
620.1	73.000000
621.1	65.000000
630.1.2	305.000000
634.1.1	95.000000
647.2	19.000000
660.1.1	16.000000
667	139.000000
671.3.8	4,200.000000
672.4.6	5,050.000000
673.1.5	5,250.000000
684.6.2	115.000000
686.1	410.000000
687.1.1	2,400.000000
703.2.2	27.500000
714.2.6	5,140.000000
715.2.9	5,098.000000
718.3.3	1,070.000000
719.1.3	1,100.000000
720.11	9.000000
729.1.2	972.000000
730.2.5	2.300000
732.5.30	75.000000
744.9	70,000.000000
755.10	13,260.000000
757.1.4	17,490.000000
760.1.4	4,800.000000
801.3.2	.220500
801.7.1	1.900000
812.1.2	.147700
812.2.3	1.518700
813.2.3	2.436600
816.3.2	.791600
820.5.1	.740800
820.5.4	2.545300
825.6.1	.479200
826.2.1	1.700000

835.1.2	76.500000
841.3.5	192.000000
842.3.2	81.400000
848.1.2	34.200000
852.1.6	995.000000
855.1.13	2,732.000000
858.1.2	3.200000
859.1.2	5.000000
865.13.10	19,950.000000
865.13.9	16,500.000000
865.8.3	41.000000
867.1.22	75,800.000000
871.7.4	49.520000
872.23.1	4.400000
880.1.2	.780000
885.1.2	20.000000
890.1.1	120.000000
910.2.5	9,500.000000
911.1.17	3,430.000000
912.1.5	3,694.000000
913.1.9	68.900000
914.1.8	155.000000
915.1.6	345.000000
915.3.10	13,101.000000
916.1.3	
916.2.3	
916.3.3	
917.1	7,780.000000
918.1.1	2,010.000000
920.1.1	7,479.000000
923.1.1	61.620000
923.2.1	161.400000
925.1.1	4,600.000000
931.1.5	370.000000
931.2.4	1,070.000000
932.4.2	348.000000
933.1.1	15.500000
934.1.1	324.000000
935.1.1	76.500000
950.1.1	5.900000
951.1.7	701.000000
951.2.2	12,650.000000
952.1.4	331.800000
953.1.3	26,500.000000

1	1				
026		1.100000 x	.099900 =	.109890	
297.1		1.200000 x	1.910000 =	2.292000	
582.2		1.300000 x	27.000000 =	35.100000	
002		1.300000 x	17.205541 =	22.367203	
003		1.300000 x	20.290479 =	26.377623	

			T.E =	86.246716	
10	10				
581.2		1.200000 x	9.090000 =	10.908000	
003		.300000 x	20.290479 =	6.087144	
001		.300000 x	15.643441 =	4.693032	

			T.E =	21.688176	
100	100				
931.1.5		1.000000 x	370.000000 =	370.000000	
003		4.000000 x	20.290479 =	81.161916	
002		6.000000 x	17.205541 =	103.233246	

			T.E =	554.395162	
101	101				
931.2.4		1.000000 x	1,070.000000 =	1,070.000000	
002		9.000000 x	17.205541 =	154.849869	
003		6.000000 x	20.290479 =	121.742874	

			T.E =	1,346.592743	
102	102				
820.5.4		1.020000 x	2.545300 =	2.596206	
002		.200000 x	17.205541 =	3.441108	
003		.200000 x	20.290479 =	4.058096	

			T.E =	10.095410	
103	103				
932.4.2		1.000000 x	348.000000 =	348.000000	
002		2.500000 x	17.205541 =	43.013853	
003		2.500000 x	20.290479 =	50.726198	

			T.E =	441.740050	
104	104				
933.1.1		1.000000 x	15.500000 =	15.500000	
003		1.200000 x	20.290479 =	24.348575	
002		1.200000 x	17.205541 =	20.646649	

			T.E =	60.495224	

105	105				
934.1.1		1.000000 x	324.000000 =	324.000000	
002		2.000000 x	17.205541 =	34.411082	
003		2.000000 x	20.290479 =	40.580958	

			T.E =	398.992040	
106	106				
951.1.7		1.030000 x	701.000000 =	722.030000	
002		4.000000 x	17.205541 =	68.822164	
003		4.000000 x	20.290479 =	81.161916	

			T.E =	872.014080	
107	107				
952.1.4		1.030000 x	331.800000 =	341.754000	
002		1.000000 x	17.205541 =	17.205541	
003		1.000000 x	20.290479 =	20.290479	

			T.E =	379.250020	
108	108				
951.2.2		1.030000 x	12,650.000000 =	13,029.500000	
003		6.000000 x	20.290479 =	121.742874	
002		6.000000 x	17.205541 =	103.233246	

			T.E =	13,254.476120	
109	109				
953.1.3		1.030000 x	26,500.000000 =	27,295.000000	
003		12.000000 x	20.290479 =	243.485748	
002		12.000000 x	17.205541 =	206.466492	

			T.E =	27,744.952240	
11	11				
603.3		1.030000 x	5.650000 =	5.819500	
003		.500000 x	20.290479 =	10.145240	

			T.E =	15.964740	
110	110				
950.1.1		1.050000 x	5.900000 =	6.195000	
002		.200000 x	17.205541 =	3.441108	
003		.200000 x	20.290479 =	4.058096	

			T.E =	13.694204	

12	12				
605.3.5		1.050000 x	136.000000 =	142.800000	
002		.600000 x	17.205541 =	10.323325	
003		.600000 x	20.290479 =	12.174287	

			T.E =	165.297612	
13	13				
619.2.2		1.030000 x	44.600000 =	45.938000	
002		.400000 x	17.205541 =	6.882216	
003		.400000 x	20.290479 =	8.116192	

			T.E =	60.936408	
14	14				
026		15.000000 x	.099900 =	1.498500	
620.1		1.000000 x	73.000000 =	73.000000	
003		2.000000 x	20.290479 =	40.580958	
002		2.000000 x	17.205541 =	34.411082	

			T.E =	149.490540	
15	15				
621.1		1.000000 x	65.000000 =	65.000000	
003		2.000000 x	20.290479 =	40.580958	
002		2.000000 x	17.205541 =	34.411082	
621.1		.100000 x	65.000000 =	6.500000	

			T.E =	146.492040	
16	16				
630.1.2		1.000000 x	305.000000 =	305.000000	
003		3.000000 x	20.290479 =	60.871437	
002		3.000000 x	17.205541 =	51.616623	
630.1.2		.050000 x	305.000000 =	15.250000	

			T.E =	432.738060	
17	17				
634.1.1		1.200000 x	95.000000 =	114.000000	
003		2.000000 x	20.290479 =	40.580958	
002		.200000 x	17.205541 =	3.441108	
634.1.1		.050000 x	95.000000 =	4.750000	

			T.E =	162.772066	
18	18				
647.2		1.000000 x	19.000000 =	19.000000	
003		.200000 x	20.290479 =	4.058096	

			T.E =	23.058096	

19	19				
660.1.1		1.030000 x	16.000000 =	16.480000	
003		.200000 x	20.290479 =	4.058096	
002		.200000 x	17.205541 =	3.441108	

			T.E =	23.979204	
2	2				
561		5.320000 x	2.030000 =	10.799600	
003		.600000 x	20.290479 =	12.174287	
002		.600000 x	17.205541 =	10.323325	

			T.E =	33.297212	
20	20				
667		1.000000 x	139.000000 =	139.000000	
667		.020000 x	139.000000 =	2.780000	
003		4.000000 x	20.290479 =	81.161916	
002		4.000000 x	17.205541 =	68.822164	

			T.E =	291.764080	
21	21				
671.3.8		1.000000 x	4,200.000000 =	4,200.000000	
671.3.8		.100000 x	4,200.000000 =	420.000000	
002		20.000000 x	17.205541 =	344.110820	
003		20.000000 x	20.290479 =	405.809580	

			T.E =	5,369.920400	
22	22				
672.4.6		1.000000 x	5,050.000000 =	5,050.000000	
672.4.6		.100000 x	5,050.000000 =	505.000000	
003		20.000000 x	20.290479 =	405.809580	
002		20.000000 x	17.205541 =	344.110820	

			T.E =	6,304.920400	
23	23				
673.1.5		1.000000 x	5,250.000000 =	5,250.000000	
003		25.000000 x	20.290479 =	507.261975	
002		25.000000 x	17.205541 =	430.138525	
687.1.1		.020000 x	2,400.000000 =	48.000000	
687.1.1		1.000000 x	2,400.000000 =	2,400.000000	
673.1.5		.020000 x	5,250.000000 =	105.000000	

			T.E =	8,740.400500	

24	24				
684.6.2		1.000000 x	115.000000 =	115.000000	
003		1.000000 x	20.290479 =	20.290479	
684.6.2		.020000 x	115.000000 =	2.300000	
002		1.000000 x	17.205541 =	17.205541	

 T.E = 154.796020

25	25				
686.1		1.000000 x	410.000000 =	410.000000	
003		4.000000 x	20.290479 =	81.161916	
002		4.000000 x	17.205541 =	68.822164	
686.1		.020000 x	410.000000 =	8.200000	

 T.E = 568.184080

26	26				
703.2.2		1.020000 x	27.500000 =	28.050000	
003		.250000 x	20.290479 =	5.072620	
002		.250000 x	17.205541 =	4.301385	

 T.E = 37.424005

27	27				
714.2.6		1.000000 x	5,140.000000 =	5,140.000000	
003		10.000000 x	20.290479 =	202.904790	
002		10.000000 x	17.205541 =	172.055410	
714.2.6		.020000 x	5,140.000000 =	102.800000	
001		5.000000 x	15.643441 =	78.217205	

 T.E = 5,695.977405

28	28				
715.2.9		1.000000 x	5,098.000000 =	5,098.000000	
003		12.000000 x	20.290479 =	243.485748	
002		12.000000 x	17.205541 =	206.466492	
001		6.000000 x	15.643441 =	93.860646	
715.2.9		.020000 x	5,098.000000 =	101.960000	

 T.E = 5,743.772886

29	29				
718.3.3		1.000000 x	1,070.000000 =	1,070.000000	
002		8.000000 x	17.205541 =	137.644328	
718.3.3		.050000 x	1,070.000000 =	53.500000	
003		8.000000 x	20.290479 =	162.323832	

 T.E = 1,423.468160

3	3			
026		1.200000 x	.099900 =	.119880
588.3		1.300000 x	.000000 =	.000000
003		1.200000 x	20.290479 =	24.348575
002		1.200000 x	17.205541 =	20.646649

 T.E =

30	30			
719.1.3		1.000000 x	1,100.000000 =	1,100.000000
719.1.3		.100000 x	1,100.000000 =	110.000000
003		16.000000 x	20.290479 =	324.647664
002		16.000000 x	17.205541 =	275.288656
001		8.000000 x	15.643441 =	125.147528

 T.E = 1,935.083848

31	31			
720.11		1.020000 x	9.000000 =	9.180000
003		.300000 x	20.290479 =	6.087144

 T.E = 15.267144

32	32			
729.1.2		1.000000 x	972.000000 =	972.000000
002		2.000000 x	17.205541 =	34.411082
003		2.000000 x	20.290479 =	40.580958
729.1.2		.030000 x	972.000000 =	29.160000

 T.E = 1,076.152040

33	33			
757.1.4		1.000000 x	17,490.000000 =	17,490.000000
757.1.4		.050000 x	17,490.000000 =	874.500000
002		15.000000 x	17.205541 =	258.083115
003		15.000000 x	20.290479 =	304.357185
001		7.000000 x	15.643441 =	109.504087

 T.E = 19,036.444387

34	34			
273		1.000000 x	1.084300 =	1.084300
003		.300000 x	20.290479 =	6.087144
002		.300000 x	17.205541 =	5.161662
273		.100000 x	1.084300 =	.108430

 T.E = 12.441536

35	35				
730.2.5		1.050000 x	2.300000 =	2.415000	
003		.120000 x	20.290479 =	2.434857	
002		.120000 x	17.205541 =	2.064665	
730.2.5		.250000 x	2.300000 =	.575000	

 T.E = 7.489522

36	36				
732.5.30		1.050000 x	75.000000 =	78.750000	
003		.400000 x	20.290479 =	8.116192	
002		.400000 x	17.205541 =	6.882216	

 T.E = 93.748408

37	37				
744.9		1.000000 x	70,000.000000 =	70,000.000000	
744.9		.020000 x	70,000.000000 =	1,400.000000	
001		10.000000 x	15.643441 =	156.434410	
002		20.000000 x	17.205541 =	344.110820	
003		20.000000 x	20.290479 =	405.809580	

 T.E = 72,306.354810

38	38				
755.10		1.000000 x	13,260.000000 =	13,260.000000	
755.10		.020000 x	13,260.000000 =	265.200000	
001		10.000000 x	15.643441 =	156.434410	
002		10.000000 x	17.205541 =	172.055410	
003		10.000000 x	20.290479 =	202.904790	

 T.E = 14,056.594610

39	39				
760.1.4		1.000000 x	4,800.000000 =	4,800.000000	
760.1.4		.050000 x	4,800.000000 =	240.000000	
002		3.500000 x	17.205541 =	60.219394	
003		3.500000 x	20.290479 =	71.016677	

 T.E = 5,171.236070

4	4				
565.3		1.250000 x	3.800000 =	4.750000	
002		.600000 x	17.205541 =	10.323325	
003		.600000 x	20.290479 =	12.174287	

 T.E = 27.247612

40	40				
036		3.000000 x	.090700 =	.272100	
003		.450000 x	20.290479 =	9.130716	
002		.450000 x	17.205541 =	7.742493	
510		.350000 x	3.020000 =	1.057000	
511		.250000 x	.620000 =	.155000	
513		.250000 x	1.200000 =	.300000	

			T.E =	18.657309	
41	41				
801.3.2		1.050000 x	.220500 =	.231525	
003		.100000 x	20.290479 =	2.029048	
801.3.2		.105000 x	.220500 =	.023153	
002		.100000 x	17.205541 =	1.720554	

			T.E =	4.004280	
42	42				
801.7.1		1.050000 x	1.900000 =	1.995000	
003		.200000 x	20.290479 =	4.058096	
002		.200000 x	17.205541 =	3.441108	
801.7.1		.210000 x	1.900000 =	.399000	

			T.E =	9.893204	
43	43				
812.1.2		1.050000 x	.147700 =	.155085	
003		.020000 x	20.290479 =	.405810	
002		.020000 x	17.205541 =	.344111	

			T.E =	.905005	
44	44				
812.2.3		1.050000 x	1.518700 =	1.594635	
003		.060000 x	20.290479 =	1.217429	
002		.060000 x	17.205541 =	1.032332	

			T.E =	3.844396	
45	45				
813.2.3		1.050000 x	2.436600 =	2.558430	
813.2.3		.105000 x	2.436600 =	.255843	
003		.050000 x	20.290479 =	1.014524	
002		.050000 x	17.205541 =	.860277	

			T.E =	4.689074	

46	46				
816.3.2		.157500 x	.791600 =	.124677	
816.3.2		1.050000 x	.791600 =	.831180	
002		.120000 x	17.205541 =	2.064665	
003		.120000 x	20.290479 =	2.434857	

			T.E =	5.455379	
47	47				
820.5.1		1.050000 x	.740800 =	.777840	
820.5.1		.157500 x	.740800 =	.116676	
003		.140000 x	20.290479 =	2.840667	
002		.140000 x	17.205541 =	2.408776	

			T.E =	6.143959	
48	48				
825.6.1		1.050000 x	.479200 =	.503160	
003		.100000 x	20.290479 =	2.029048	
002		.100000 x	17.205541 =	1.720554	
825.6.1		.157500 x	.479200 =	.075474	

			T.E =	4.328236	
49	49				
826.2.1		1.000000 x	1.700000 =	1.700000	
003		.200000 x	20.290479 =	4.058096	

			T.E =	5.758096	
5	5				
566.3		1.250000 x	5.050000 =	6.312500	
002		.600000 x	17.205541 =	10.323325	
003		.600000 x	20.290479 =	12.174287	

			T.E =	28.810112	
50	50				
842.3.2		1.000000 x	81.400000 =	81.400000	
842.3.2		.030000 x	81.400000 =	2.442000	
002		.500000 x	17.205541 =	8.602771	
003		.500000 x	20.290479 =	10.145240	

			T.E =	102.590010	
51	51				
841.3.5		1.000000 x	192.000000 =	192.000000	
841.3.5		.030000 x	192.000000 =	5.760000	
003		1.000000 x	20.290479 =	20.290479	
002		1.000000 x	17.205541 =	17.205541	

			T.E =	235.256020	

52	52				
835.1.2		1.050000 x	76.500000 =	80.325000	
003		3.000000 x	20.290479 =	60.871437	
002		3.000000 x	17.205541 =	51.616623	

			T.E =	192.813060	
53	53				
848.1.2		1.020000 x	34.200000 =	34.884000	
003		.200000 x	20.290479 =	4.058096	

			T.E =	38.942096	
54	54				
858.1.2		1.020000 x	3.200000 =	3.264000	
003		.200000 x	20.290479 =	4.058096	

			T.E =	7.322096	
55	55				
859.1.2		1.020000 x	5.000000 =	5.100000	
003		.200000 x	20.290479 =	4.058096	

			T.E =	9.158096	
56	56				
865.8.3		1.050000 x	41.000000 =	43.050000	
002		2.000000 x	17.205541 =	34.411082	
003		2.000000 x	20.290479 =	40.580958	

			T.E =	118.042040	
57	57				
865.13.9		1.020000 x	16,500.000000 =	16,830.000000	
002		25.000000 x	17.205541 =	430.138525	
001		10.000000 x	15.643441 =	156.434410	
003		25.000000 x	20.290479 =	507.261975	

			T.E =	17,923.834910	
58	58				
867.1.22		1.000000 x	75,800.000000 =	75,800.000000	
867.1.22		.030000 x	75,800.000000 =	2,274.000000	
001		130.000000 x	15.643441 =	2,033.647330	
003		130.000000 x	20.290479 =	2,637.762270	
002		130.000000 x	17.205541 =	2,236.720330	

			T.E =	84,982.129930	

59	59				
871.7.4		1.000000 x	49.520000 =	49.520000	
002		1.200000 x	17.205541 =	20.646649	
003		1.200000 x	20.290479 =	24.348575	
871.7.4		.020000 x	49.520000 =	.990400	

			T.E =	95.505624	
6	6				
567.13		1.300000 x	19.210000 =	24.973000	
003		1.000000 x	20.290479 =	20.290479	
002		1.000000 x	17.205541 =	17.205541	

			T.E =	62.469020	
60	60				
872.23.1		1.020000 x	4.400000 =	4.488000	
003		.600000 x	20.290479 =	12.174287	
002		.600000 x	17.205541 =	10.323325	
880.1.2		1.000000 x	.780000 =	.780000	

			T.E =	27.765612	
61	61				
885.1.2		1.000000 x	20.000000 =	20.000000	
002		.600000 x	17.205541 =	10.323325	
003		.600000 x	20.290479 =	12.174287	

			T.E =	42.497612	
62	62				
890.1.1		1.000000 x	120.000000 =	120.000000	
890.1.1		.050000 x	120.000000 =	6.000000	
002		2.000000 x	17.205541 =	34.411082	
003		2.000000 x	20.290479 =	40.580958	

			T.E =	200.992040	
63	63				
910.2.5		1.000000 x	9,500.000000 =	9,500.000000	
002		50.000000 x	17.205541 =	860.277050	
001		30.000000 x	15.643441 =	469.303230	
003		50.000000 x	20.290479 =	1,014.523950	
910.2.5		.020000 x	9,500.000000 =	190.000000	

			T.E =	12,034.104230	

7	7				
571.5.1		1.400000 x	2.670000 =	3.738000	
003		.300000 x	20.290479 =	6.087144	
002		.300000 x	17.205541 =	5.161662	

			T.E =	14.986806	
8	8				
572.1.7		1.350000 x	3.380000 =	4.563000	
002		.700000 x	17.205541 =	12.043879	
003		.700000 x	20.290479 =	14.203335	

			T.E =	30.810214	
80	80				
911.1.17		1.050000 x	3,430.000000 =	3,601.500000	
002		30.000000 x	17.205541 =	516.166230	
003		30.000000 x	20.290479 =	608.714370	

			T.E =	4,726.380600	
81	81				
912.1.5		1.050000 x	3,694.000000 =	3,878.700000	
002		30.000000 x	17.205541 =	516.166230	
003		30.000000 x	20.290479 =	608.714370	

			T.E =	5,003.580600	
82	82				
913.1.9		1.200000 x	68.900000 =	82.680000	
003		4.000000 x	20.290479 =	81.161916	
002		4.000000 x	17.205541 =	68.822164	

			T.E =	232.664080	
83	83				
914.1.8		1.100000 x	155.000000 =	170.500000	
002		2.000000 x	17.205541 =	34.411082	
003		2.000000 x	20.290479 =	40.580958	

			T.E =	245.492040	
84	84				
915.1.6		1.050000 x	345.000000 =	362.250000	
002		8.000000 x	17.205541 =	137.644328	
003		8.000000 x	20.290479 =	162.323832	

			T.E =	662.218160	

85	85			
915.3.10		1.050000 x	13,101.000000 =	13,756.050000
002		20.000000 x	17.205541 =	344.110820
003		20.000000 x	20.290479 =	405.809580

 T.E = 14,505.970400

86	86			
865.13.10		1.020000 x	19,950.000000 =	20,349.000000
003		40.000000 x	20.290479 =	811.619160
002		40.000000 x	17.205541 =	688.221640

 T.E = 21,848.840800

87	87			
916.1.3		1.030000 x	.000000 =	.000000
916.3.3		1.010000 x	.000000 =	.000000
916.2.3		1.020000 x	.000000 =	.000000
003		120.000000 x	20.290479 =	2,434.857480
002		120.000000 x	17.205541 =	2,064.664920

 T.E =

88	88			
917.1		1.000000 x	7,780.000000 =	7,780.000000
917.1		.030000 x	7,780.000000 =	233.400000
918.1.1		.030000 x	2,010.000000 =	60.300000
920.1.1		.030000 x	7,479.000000 =	224.370000
923.1.1		.030000 x	61.620000 =	1.848600
003		40.000000 x	20.290479 =	811.619160
002		40.000000 x	17.205541 =	688.221640
923.2.1		.030000 x	161.400000 =	4.842000
923.2.1		1.000000 x	161.400000 =	161.400000
923.1.1		1.000000 x	61.620000 =	61.620000
920.1.1		1.000000 x	7,479.000000 =	7,479.000000
918.1.1		1.000000 x	2,010.000000 =	2,010.000000

 T.E = 19,516.621400

89	89			
852.1.6		1.000000 x	995.000000 =	995.000000
855.1.13		1.000000 x	2,732.000000 =	2,732.000000
855.1.13		.020000 x	2,732.000000 =	54.640000
925.1.1		.020000 x	4,600.000000 =	92.000000
003		60.000000 x	20.290479 =	1,217.428740
002		60.000000 x	17.205541 =	1,032.332460
925.1.1		1.000000 x	4,600.000000 =	4,600.000000
852.1.6		.020000 x	995.000000 =	19.900000

 T.E = 10,743.301200

9 9

575.3
003
002

1.200000 x
.300000 x
.300000 x

.000000 =
20.290479 =
17.205541 =

.000000
6.087144
5.161662

T.E =