

ΑΤΕΟ (ΝΕΟ)

Αναλυτικά Τιμολόγια Έργων

1ο Τρίμηνο του 2012

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
211	1.243100
212	1.434100
213	1.949500
214	4.550000
215	1.081100
221	.099900
222	.116200
223	.119300
224	.070000
231	.895000
232	2.184000
233	.558700
234	.847400
235	.632700
236	.624500
237	1.218000
238	.558700
239	8.250000
241	7.750000
242	4.500000
243	2.400000
244	2.700000
251	290.000000
252	290.000000
261	15.100000
262	26.300000
263	32.400000
264	64.100000
265	115.100000
271	206.300000
281	21.300000
282	30.000000
283	36.300000
284	75.400000
301	3.860000
302	6.360000
321	.596000
322	
323	.580000
324	.580000
325	2.780000
326	1.310000
327	.540000
328	1.840000
329	.730000
351	770.000000
352	1,040.000000
353	3.630000
354	4.020000
355	.121800
401	268.420000

402	380.180000
403	103.360000
404	212.730000
405	206.720000
406	320.980000
407	55.210000
408	4.530000
409	126.080000
410	116.530000
411	27.370000
412	2.990000
413	4.530000
414	6.250000
415	8.780000
416	13.540000
417	134.530000
418	44.890000
419	4.530000
420	97.290000
421	32.560000
422	38.010000
423	12.540000
424	41.920000
425	165.330000
426	1,234.850000
427	185.840000
428	437.840000
429	77.590000
501.1M	287.610000
501.2M	322.830000
501.3M	281.740000
501.4M	199.570000
502.1M	326.260000
502.2M	478.520000
502.3M	677.380000
502.4M	901.110000
502.5M	1,590.920000
502.6M	664.960000
504.1M	297.020000
504.2M	436.790000
504.3M	220.140000
504.4M	269.060000
505.1M	639.700000
505.2M	762.190000
506.10M	383.030000
506.1M	123.390000
506.2M	134.110000
506.3M	174.620000
506.4M	199.400000
506.5M	177.030000
506.6M	209.220000
506.7M	413.070000
506.8M	247.840000
506.9M	297.410000
508.1M	18.310000
508.2M	21.970000
508.3M	31.740000
508.4M	42.730000
509.1M	92.080000

509.2M	92.080000
509.3M	96.230000
509.4M	99.910000
511.1M	11.180000
511.2M	11.180000
511.3M	14.900000
511.4M	14.900000
511.5M	16.890000
511.6M	15.650000
512.1M	1.530000
512.2M	1.980000
512.3M	1.980000
512.4M	2.590000
512.5M	2.590000
512.6M	4.420000
512.7M	4.420000
512.8M	15.260000
512.9M	21.360000
514.1M	243.560000
514.2M	249.800000
514.3M	319.750000
514.4M	337.230000
514.5M	395.930000
515.1M	140.980000
515.2M	201.400000
515.3M	302.090000
515.4M	382.650000
515.5M	483.350000
515.6M	538.730000
515.7M	619.290000
515.8M	538.730000
517.1M	509.760000
517.2M	1,372.420000
517.3M	1,568.480000
517.4M	490.150000
517.5M	509.760000
517.6M	637.190000
518.1M	958.880000
518.2M	1,917.760000
518.3M	1,917.760000
518.4M	1,917.760000
519.1M	324.160000
519.2M	324.160000
519.3M	319.840000
519.4M	283.100000
519.5M	399.800000
519.6M	259.330000
521.1M	73.160000
521.2M	73.160000
521.3M	61.910000
521.4M	74.100000
521.5M	87.230000
521.6M	98.490000
521.7M	98.490000
523.1M	93.690000
525.1M	28.730000
526.1M	156.130000
527.1M	1,282.330000
527.2M	2,369.530000

528.1M  
528.2M  
528.3M  
528.4M  
529.1M

312.250000  
349.720000  
349.720000  
374.700000  
112.410000

501	501				
501.1		.100000 x	589.311534 =	58.931153	
501.3		.150000 x	584.615534 =	87.692330	
501.4		.150000 x	544.052457 =	81.607869	
501.2		.600000 x	713.736949 =	428.242169	
			H.Δ. =	656.473521	
501.1	501.1				
211		146.190706 x	1.243100 =	181.729667	
114		6.670000 x	23.886192 =	159.320901	
211		14.619071 x	1.243100 =	18.172967	
501.1M		.800000 x	287.610000 =	230.088000	
			H.Δ. =	589.311534	
501.2	501.2				
211		216.578823 x	1.243100 =	269.229135	
114		6.670000 x	23.886192 =	159.320901	
501.2M		.800000 x	322.830000 =	258.264000	
211		21.657882 x	1.243100 =	26.922913	
			H.Δ. =	713.736949	
501.3	501.3				
211		14.619071 x	1.243100 =	18.172967	
114		6.670000 x	23.886192 =	159.320901	
501.3M		.800000 x	281.740000 =	225.392000	
211		146.190706 x	1.243100 =	181.729667	
			H.Δ. =	584.615534	
501.4	501.4				
211		164.599905 x	1.243100 =	204.614142	
211		16.459991 x	1.243100 =	20.461415	
501.4M		.800000 x	199.570000 =	159.656000	
114		6.670000 x	23.886192 =	159.320901	
			H.Δ. =	544.052457	
502	502				
502.1		.200000 x	773.501994 =	154.700399	
502.3		.400000 x	1,287.617734 =	515.047094	
502.2		.400000 x	960.093254 =	384.037302	
			H.Δ. =	1,053.784794	

502.1	502.1			
211		24.365118 x	1.243100 =	30.288278
118		2.000000 x	10.001019 =	20.002038
211		243.651176 x	1.243100 =	302.882777
114		6.670000 x	23.886192 =	159.320901
502.1M		.800000 x	326.260000 =	261.008000
			H.Δ. =	773.501994
502.2	502.2			
211		291.027794 x	1.243100 =	361.776651
211		29.102779 x	1.243100 =	36.177665
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
502.2M		.800000 x	478.520000 =	382.816000
			H.Δ. =	960.093254
502.3	502.3			
211		414.207001 x	1.243100 =	514.900723
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
502.3M		.800000 x	677.380000 =	541.904000
211		41.420700 x	1.243100 =	51.490072
			H.Δ. =	1,287.617734
503	503			
502.3		.150000 x	1,287.617734 =	193.142660
503.4		.400000 x	1,585.062550 =	634.025020
503.6		.100000 x	1,322.104543 =	132.210454
503.5		.350000 x	2,414.553103 =	845.093586
			H.Δ. =	1,804.471720
503.4	503.4			
211		50.083853 x	1.243100 =	62.259238
211		500.838528 x	1.243100 =	622.592374
502.4M		.800000 x	901.110000 =	720.888000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
			H.Δ. =	1,585.062550
503.5	503.5			
211		703.881180 x	1.243100 =	874.994695
118		2.000000 x	10.001019 =	20.002038
211		70.388118 x	1.243100 =	87.499469
114		6.670000 x	23.886192 =	159.320901
502.5M		.800000 x	1,590.920000 =	1,272.736000
			H.Δ. =	2,414.553103

503.6	503.6			
211		44.669383 x	1.243100 =	55.528510
211		446.693825 x	1.243100 =	555.285094
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
502.6M		.800000 x	664.960000 =	531.968000
				-----
			H.Δ. =	1,322.104543
504	504			
504.1		.350000 x	744.915559 =	260.720446
504.4		.100000 x	698.855394 =	69.885539
504.2		.450000 x	945.577174 =	425.509728
504.3		.100000 x	683.411559 =	68.341156
				-----
			H.Δ. =	824.456869
504.1	504.1			
211		254.480118 x	1.243100 =	316.344235
114		6.670000 x	23.886192 =	159.320901
504.1M		.800000 x	297.020000 =	237.616000
211		25.448012 x	1.243100 =	31.634424
				-----
			H.Δ. =	744.915559
504.2	504.2			
211		319.453766 x	1.243100 =	397.112977
211		31.945376 x	1.243100 =	39.711297
504.2M		.800000 x	436.790000 =	349.432000
114		6.670000 x	23.886192 =	159.320901
				-----
			H.Δ. =	945.577174
504.3	504.3			
211		25.448012 x	1.243100 =	31.634424
211		254.480118 x	1.243100 =	316.344235
114		6.670000 x	23.886192 =	159.320901
504.3M		.800000 x	220.140000 =	176.112000
				-----
			H.Δ. =	683.411559
504.4	504.4			
211		237.153812 x	1.243100 =	294.805904
211		23.715381 x	1.243100 =	29.480590
114		6.670000 x	23.886192 =	159.320901
504.4M		.800000 x	269.060000 =	215.248000
				-----
			H.Δ. =	698.855394

505	505			
505.1		.500000 x	1,199.735860 =	599.867930
505.2		.500000 x	1,297.727860 =	648.863930
-----				
			H.Δ. =	1,248.731860
505.1	505.1			
211		35.735506 x	1.243100 =	44.422808
118		4.000000 x	10.001019 =	40.004076
114		6.670000 x	23.886192 =	159.320901
505.1M		.800000 x	639.700000 =	511.760000
211		357.355061 x	1.243100 =	444.228076
-----				
			H.Δ. =	1,199.735860
505.2	505.2			
211		35.735506 x	1.243100 =	44.422808
211		357.355061 x	1.243100 =	444.228076
505.2M		.800000 x	762.190000 =	609.752000
118		4.000000 x	10.001019 =	40.004076
114		6.670000 x	23.886192 =	159.320901
-----				
			H.Δ. =	1,297.727860
506	506			
506.1		.100000 x	424.013220 =	42.401322
506.4		.350000 x	534.550084 =	187.092529
506.2		.200000 x	469.484828 =	93.896966
506.3		.350000 x	479.434631 =	167.802121
-----				
			H.Δ. =	491.192938
506.1	506.1			
211		10.675531 x	1.243100 =	13.270753
118		2.000000 x	10.001019 =	20.002038
506.1M		.800000 x	123.390000 =	98.712000
114		6.670000 x	23.886192 =	159.320901
211		106.755312 x	1.243100 =	132.707528
-----				
			H.Δ. =	424.013220
506.2	506.2			
211		13.373742 x	1.243100 =	16.624899
506.2M		.800000 x	134.110000 =	107.288000
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
211		133.737423 x	1.243100 =	166.248991
-----				
			H.Δ. =	469.484828

506.3	506.3			
211		117.313529 x	1.243100 =	145.832448
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
506.3M		.800000 x	174.620000 =	139.696000
211		11.731353 x	1.243100 =	14.583245
-----				
			H.Δ. =	479.434631
506.4	506.4			
211		14.312251 x	1.243100 =	17.791559
211		143.122505 x	1.243100 =	177.915586
506.4M		.800000 x	199.400000 =	159.520000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
-----				
			H.Δ. =	534.550084
507	507			
507.5		.100000 x	577.612048 =	57.761205
507.8		.100000 x	639.072517 =	63.907252
507.10		.250000 x	942.931665 =	235.732916
507.9		.350000 x	744.498952 =	260.574633
507.6		.100000 x	1.524292 =	70.763425
507.7		.100000 x	4.312528 =	88.675582
-----				
			H.Δ. =	777.415012
507.10	507.10			
211		334.343559 x	165.153677 =	415.622478
118		2.000000 x	1.301317 =	20.002038
211		33.434356 x	2.647364 =	41.562248
114		6.670000 x	75.839126 =	159.320901
506.10M		.800000 x	571.835454 =	306.424000
-----				
			H.Δ. =	942.931665
507.5	507.5			
211		187.701647 x	= =	233.331917
506.5M		.800000 x	T.E =	141.624000
114		6.670000 x	T.E =	159.320901
118		2.000000 x	10.001019 =	20.002038
211		18.770165 x	1.243100 =	23.333192
-----				
			H.Δ. =	577.612048

507.6	507.6			
211		263.955441 x	1.243100 =	328.123009
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
506.6M		.800000 x	209.220000 =	167.376000
211		26.395544 x	1.243100 =	32.812301
		-----		
			H.Δ. =	707.634248
507.7	507.7			
211		27.568679 x	1.243100 =	34.270625
211		275.686794 x	1.243100 =	342.706254
506.7M		.800000 x	413.070000 =	330.456000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	886.755817
507.8	507.8			
211		191.221052 x	1.243100 =	237.706890
118		2.000000 x	10.001019 =	20.002038
211		19.122105 x	1.243100 =	23.770689
114		6.670000 x	23.886192 =	159.320901
506.8M		.800000 x	247.840000 =	198.272000
		-----		
			H.Δ. =	639.072517
507.9	507.9			
211		23.931960 x	1.243100 =	29.749819
211		239.319599 x	1.243100 =	297.498194
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
506.9M		.800000 x	297.410000 =	237.928000
		-----		
			H.Δ. =	744.498952
508	508			
508.1		.250000 x	369.100564 =	92.275141
508.4		.250000 x	470.448567 =	117.612142
508.2		.250000 x	420.153272 =	105.038318
508.3		.250000 x	427.969272 =	106.992318
		-----		
			H.Δ. =	421.917919
508.1	508.1			
211		28.155247 x	1.243100 =	34.999788
116		13.340000 x	20.419486 =	272.395943
115		2.000000 x	21.778427 =	43.556854
508.1M		.800000 x	18.310000 =	14.648000
211		2.815525 x	1.243100 =	3.499979
		-----		
			H.Δ. =	369.100564

508.2	508.2			
211		6.334931 x	1.243100 =	7.874953
211		63.349306 x	1.243100 =	78.749522
508.2M		.800000 x	21.970000 =	17.576000
116		13.340000 x	20.419486 =	272.395943
115		2.000000 x	21.778427 =	43.556854
-----				
			H.Δ. =	420.153272
508.3	508.3			
211		63.349306 x	1.243100 =	78.749522
116		13.340000 x	20.419486 =	272.395943
211		6.334931 x	1.243100 =	7.874953
115		2.000000 x	21.778427 =	43.556854
508.3M		.800000 x	31.740000 =	25.392000
-----				
			H.Δ. =	427.969272
508.4	508.4			
211		87.985147 x	1.243100 =	109.374336
211		8.798515 x	1.243100 =	10.937434
115		2.000000 x	21.778427 =	43.556854
116		13.340000 x	20.419486 =	272.395943
508.4M		.800000 x	42.730000 =	34.184000
-----				
			H.Δ. =	470.448567
509	509			
509.1		.100000 x	574.272270 =	57.427227
509.4		.500000 x	613.853378 =	306.926689
509.2		.200000 x	518.743761 =	103.748752
509.3		.200000 x	638.673632 =	127.734726
-----				
			H.Δ. =	595.837395
509.1	509.1			
211		284.259705 x	1.243100 =	353.363239
117		6.670000 x	16.777917 =	111.908706
509.1M		.800000 x	92.080000 =	73.664000
211		28.425971 x	1.243100 =	35.336325
-----				
			H.Δ. =	574.272270
509.2	509.2			
211		243.651176 x	1.243100 =	302.882777
211		24.365118 x	1.243100 =	30.288278
509.2M		.800000 x	92.080000 =	73.664000
117		6.670000 x	16.777917 =	111.908706
-----				
			H.Δ. =	518.743761

509.3	509.3			
211		32.892909 x	1.243100 =	40.889175
211		328.929089 x	1.243100 =	408.891751
117		6.670000 x	16.777917 =	111.908706
509.3M		.800000 x	96.230000 =	76.984000
			H.Δ. =	638.673632
509.4	509.4			
211		308.624825 x	1.243100 =	383.651520
211		30.862482 x	1.243100 =	38.365151
117		6.670000 x	16.777917 =	111.908706
509.4M		.800000 x	99.910000 =	79.928000
			H.Δ. =	613.853378
511	511			
511.1		.150000 x	391.936500 =	58.790475
511.4		.225000 x	395.319709 =	88.946935
511.5		.125000 x	396.911709 =	49.613964
511.6		.125000 x	395.512500 =	49.439063
511.3		.225000 x	394.912500 =	88.855313
511.2		.150000 x	390.307663 =	58.546149
			H.Δ. =	394.191898
511.1	511.1			
211		.496326 x	1.243100 =	.616983
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
511.1M		.800000 x	11.180000 =	8.944000
211		4.963265 x	1.243100 =	6.169835
			H.Δ. =	391.936500
511.2	511.2			
211		.377208 x	1.243100 =	.468907
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
511.2M		.800000 x	11.180000 =	8.944000
211		3.772081 x	1.243100 =	4.689074
			H.Δ. =	390.307663
511.3	511.3			
211		4.963265 x	1.243100 =	6.169835
211		.496326 x	1.243100 =	.616983
511.3M		.800000 x	14.900000 =	11.920000
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
			H.Δ. =	394.912500

511.4	511.4			
211		5.261061 x	1.243100 =	6.540025
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
511.4M		.800000 x	14.900000 =	11.920000
211		.526106 x	1.243100 =	.654002
		-----		
			H.Δ. =	395.319709
511.5	511.5			
211		5.261061 x	1.243100 =	6.540025
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
511.5M		.800000 x	16.890000 =	13.512000
211		.526106 x	1.243100 =	.654002
		-----		
			H.Δ. =	396.911709
511.6	511.6			
211		4.963265 x	1.243100 =	6.169835
112		13.340000 x	17.312112 =	230.943574
511.6M		.800000 x	15.650000 =	12.520000
115		6.670000 x	21.778427 =	145.262108
211		.496326 x	1.243100 =	.616983
		-----		
			H.Δ. =	395.512500
512	512			
512.1		.200000 x	105.962021 =	21.192404
512.4		.200000 x	156.941619 =	31.388324
512.5		.200000 x	159.409553 =	31.881911
512.2		.200000 x	110.023922 =	22.004784
512.3		.200000 x	113.725821 =	22.745164
		-----		
			H.Δ. =	129.212587
512.1	512.1			
211		1.804824 x	1.243100 =	2.243577
117		3.000000 x	16.777917 =	50.333751
112		3.000000 x	17.312112 =	51.936336
512.1M		.800000 x	1.530000 =	1.224000
211		.180482 x	1.243100 =	.224357
		-----		
			H.Δ. =	105.962021

512.2	512.2			
211		4.512059 x	1.243100 =	5.608941
211		.451206 x	1.243100 =	.560894
512.2M		.800000 x	1.980000 =	1.584000
117		3.000000 x	16.777917 =	50.333751
112		3.000000 x	17.312112 =	51.936336
		-----		
			H.Δ. =	110.023922
512.3	512.3			
211		.721929 x	1.243100 =	.897430
117		3.000000 x	16.777917 =	50.333751
211		7.219294 x	1.243100 =	8.974304
112		3.000000 x	17.312112 =	51.936336
512.3M		.800000 x	1.980000 =	1.584000
		-----		
			H.Δ. =	113.725821
512.4	512.4			
211		1.353618 x	1.243100 =	1.682683
211		13.536176 x	1.243100 =	16.826820
112		4.000000 x	17.312112 =	69.248448
117		4.000000 x	16.777917 =	67.111668
512.4M		.800000 x	2.590000 =	2.072000
		-----		
			H.Δ. =	156.941619
512.5	512.5			
211		15.341000 x	1.243100 =	19.070397
117		4.000000 x	16.777917 =	67.111668
112		4.000000 x	17.312112 =	69.248448
512.5M		.800000 x	2.590000 =	2.072000
211		1.534100 x	1.243100 =	1.907040
		-----		
			H.Δ. =	159.409553
512A	512A			
512.1		.333333 x	105.962021 =	35.320638
512.2		.333333 x	110.023922 =	36.674604
512.3		.333333 x	113.725821 =	37.908569
		-----		
			H.Δ. =	109.903811
512B	512B			
512.4		.500000 x	156.941619 =	78.470810
512.5		.500000 x	159.409553 =	79.704777
		-----		
			H.Δ. =	158.175586

513	513			
513.6		.250000 x	211.005151 =	52.751288
513.9		.250000 x	276.551633 =	69.137908
513.8		.250000 x	263.033863 =	65.758466
513.7		.250000 x	223.344819 =	55.836205
		-----		
			H.Δ. =	243.483867
513.6	513.6			
211		2.707235 x	1.243100 =	3.365364
117		5.000000 x	16.777917 =	83.889585
112		5.000000 x	17.312112 =	86.560560
211		27.072353 x	1.243100 =	33.653642
512.6M		.800000 x	4.420000 =	3.536000
		-----		
			H.Δ. =	211.005151
513.7	513.7			
211		3.609647 x	1.243100 =	4.487152
512.7M		.800000 x	4.420000 =	3.536000
117		5.000000 x	16.777917 =	83.889585
112		5.000000 x	17.312112 =	86.560560
211		36.096470 x	1.243100 =	44.871522
		-----		
			H.Δ. =	223.344819
513.8	513.8			
211		1.714582 x	1.243100 =	2.131397
211		17.145823 x	1.243100 =	21.313973
512.8M		.800000 x	15.260000 =	12.208000
117		6.670000 x	16.777917 =	111.908706
112		6.670000 x	17.312112 =	115.471787
		-----		
			H.Δ. =	263.033863
513.9	513.9			
211		23.462706 x	1.243100 =	29.166490
211		2.346271 x	1.243100 =	2.916649
117		6.670000 x	16.777917 =	111.908706
112		6.670000 x	17.312112 =	115.471787
512.9M		.800000 x	21.360000 =	17.088000
		-----		
			H.Δ. =	276.551633
513A	513A			
513.6		.500000 x	211.005151 =	105.502576
513.7		.500000 x	223.344819 =	111.672410
		-----		
			H.Δ. =	217.174985



514.5	514.5			
211		18.048235 x	1.243100 =	22.435761
114		13.340000 x	23.886192 =	318.641801
514.5M		.800000 x	395.930000 =	316.744000
211		180.482353 x	1.243100 =	224.357613
		-----		
			H.Δ. =	882.179175
515	515			
515.1		.200000 x	382.668332 =	76.533666
515.2		.200000 x	468.516925 =	93.703385
515.4		.200000 x	687.554938 =	137.510988
515.5		.200000 x	812.537743 =	162.507549
515.3		.200000 x	622.119765 =	124.423953
		-----		
			H.Δ. =	594.679541
515.1	515.1			
211		8.085609 x	1.243100 =	10.051221
515.1M		.800000 x	140.980000 =	112.784000
211		80.856094 x	1.243100 =	100.512210
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	382.668332
515.2	515.2			
211		10.828941 x	1.243100 =	13.461457
211		108.289412 x	1.243100 =	134.614568
114		6.670000 x	23.886192 =	159.320901
515.2M		.800000 x	201.400000 =	161.120000
		-----		
			H.Δ. =	468.516925
515.3	515.3			
211		16.171219 x	1.243100 =	20.102442
515.3M		.800000 x	302.090000 =	241.672000
114		6.670000 x	23.886192 =	159.320901
211		161.712189 x	1.243100 =	201.024422
		-----		
			H.Δ. =	622.119765
515.4	515.4			
211		16.243412 x	1.243100 =	20.192185
114		6.670000 x	23.886192 =	159.320901
515.4M		.800000 x	382.650000 =	306.120000
211		162.434118 x	1.243100 =	201.921852
		-----		
			H.Δ. =	687.554938

515.5	515.5			
211		194.920940 x	1.243100 =	242.306221
515.5M		.800000 x	483.350000 =	386.680000
114		6.670000 x	23.886192 =	159.320901
211		19.492094 x	1.243100 =	24.230622
		-----		
			H.Δ. =	812.537743
516	516			
515.5		.150000 x	812.537743 =	121.880661
516.6		.150000 x	876.585216 =	131.487782
516.8		.350000 x	953.584749 =	333.754662
516.7		.350000 x	1,024.942963 =	358.730037
		-----		
			H.Δ. =	945.853143
516.6	516.6			
211		209.359530 x	1.243100 =	260.254832
114		6.670000 x	23.886192 =	159.320901
515.6M		.800000 x	538.730000 =	430.984000
211		20.935953 x	1.243100 =	26.025483
		-----		
			H.Δ. =	876.585216
516.7	516.7			
211		27.072353 x	1.243100 =	33.653642
114		6.670000 x	23.886192 =	159.320901
515.7M		.800000 x	619.290000 =	495.432000
211		270.723530 x	1.243100 =	336.536420
		-----		
			H.Δ. =	1,024.942963
516.8	516.8			
211		265.670025 x	1.243100 =	330.254408
114		6.670000 x	23.886192 =	159.320901
211		26.567002 x	1.243100 =	33.025440
515.8M		.800000 x	538.730000 =	430.984000
		-----		
			H.Δ. =	953.584749
517	517			
517.1		.100000 x	1,257.383379 =	125.738338
517.2		.250000 x	2,231.323761 =	557.830940
517.3		.250000 x	2,560.927121 =	640.231780
517.4		.100000 x	1,149.147865 =	114.914787
517.6		.200000 x	1,421.025722 =	284.205144
517.5		.100000 x	1,226.534208 =	122.653421
		-----		
			H.Δ. =	1,845.574410

517.1	517.1			
211		15.792206 x	1.243100 =	19.631291
111		20.010000 x	15.741598 =	314.989376
114		13.340000 x	23.886192 =	318.641801
211		157.922058 x	1.243100 =	196.312910
517.1M		.800000 x	509.760000 =	407.808000
			H.Δ. =	1,257.383379
517.2	517.2			
211		365.476765 x	1.243100 =	454.324167
114		13.340000 x	23.886192 =	318.641801
111		20.010000 x	15.741598 =	314.989376
211		36.547677 x	1.243100 =	45.432417
517.2M		.800000 x	1,372.420000 =	1,097.936000
			H.Δ. =	2,231.323761
517.3	517.3			
211		49.181441 x	1.243100 =	61.137449
114		13.340000 x	23.886192 =	318.641801
111		20.010000 x	15.741598 =	314.989376
517.3M		.800000 x	1,568.480000 =	1,254.784000
211		491.814411 x	1.243100 =	611.374494
			H.Δ. =	2,560.927121
517.4	517.4			
211		9.024118 x	1.243100 =	11.217881
211		90.241177 x	1.243100 =	112.178807
517.4M		.800000 x	490.150000 =	392.120000
114		13.340000 x	23.886192 =	318.641801
111		20.010000 x	15.741598 =	314.989376
			H.Δ. =	1,149.147865
517.5	517.5			
211		135.361765 x	1.243100 =	168.268210
114		13.340000 x	23.886192 =	318.641801
211		13.536176 x	1.243100 =	16.826820
111		20.010000 x	15.741598 =	314.989376
517.5M		.800000 x	509.760000 =	407.808000
			H.Δ. =	1,226.534208

517.6	517.6			
211		20.304265 x	1.243100 =	25.240232
211		203.042646 x	1.243100 =	252.402313
111		20.010000 x	15.741598 =	314.989376
114		13.340000 x	23.886192 =	318.641801
517.6M		.800000 x	637.190000 =	509.752000
		-----		
			H.Δ. =	1,421.025722
518	518			
518.1		.250000 x	1,946.955702 =	486.738926
518.4		.250000 x	2,783.161845 =	695.790461
518.2		.250000 x	2,714.059702 =	678.514926
518.3		.250000 x	2,748.610774 =	687.152694
		-----		
			H.Δ. =	2,548.197006
518.1	518.1			
211		265.309059 x	1.243100 =	329.805691
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
114		20.010000 x	23.886192 =	477.962702
518.1M		.800000 x	958.880000 =	767.104000
211		26.530906 x	1.243100 =	32.980569
		-----		
			H.Δ. =	1,946.955702
518.2	518.2			
211		26.530906 x	1.243100 =	32.980569
211		265.309059 x	1.243100 =	329.805691
518.2M		.800000 x	1,917.760000 =	1,534.208000
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
114		20.010000 x	23.886192 =	477.962702
		-----		
			H.Δ. =	2,714.059702
518.3	518.3			
211		290.576588 x	1.243100 =	361.215757
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
211		29.057659 x	1.243100 =	36.121576
114		20.010000 x	23.886192 =	477.962702
518.3M		.800000 x	1,917.760000 =	1,534.208000
		-----		
			H.Δ. =	2,748.610774

518.4	518.4			
211		31.584412 x	1.243100 =	39.262583
211		315.844116 x	1.243100 =	392.625821
114		20.010000 x	23.886192 =	477.962702
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
518.4M		.800000 x	1,917.760000 =	1,534.208000
			H.Δ. =	2,783.161845
519	519			
519.1		.050000 x	809.487710 =	40.474386
519.6		.300000 x	716.714365 =	215.014310
519.5		.100000 x	1,042.443236 =	104.244324
519.2		.050000 x	861.619465 =	43.080973
519.4		.200000 x	780.646759 =	156.129352
519.3		.300000 x	818.059543 =	245.417863
			H.Δ. =	804.361207
519.1	519.1			
211		171.277754 x	1.243100 =	212.915376
116		13.340000 x	20.419486 =	272.395943
115		2.000000 x	21.778427 =	43.556854
519.1M		.800000 x	324.160000 =	259.328000
211		17.127775 x	1.243100 =	21.291537
			H.Δ. =	809.487710
519.2	519.2			
211		234.627058 x	1.243100 =	291.664896
211		23.462706 x	1.243100 =	29.166490
519.2M		.800000 x	324.160000 =	259.328000
116		6.670000 x	20.419486 =	136.197972
115		6.670000 x	21.778427 =	145.262108
			H.Δ. =	861.619465
519.3	519.3			
211		20.529868 x	1.243100 =	25.520679
116		6.670000 x	20.419486 =	136.197972
211		205.298676 x	1.243100 =	255.206784
115		6.670000 x	21.778427 =	145.262108
519.3M		.800000 x	319.840000 =	255.872000
			H.Δ. =	818.059543

519.4	519.4			
211		199.433001 x	1.243100 =	247.915164
211		19.943300 x	1.243100 =	24.791516
115		6.670000 x	21.778427 =	145.262108
116		6.670000 x	20.419486 =	136.197972
519.4M		.800000 x	283.100000 =	226.480000
				-----
			H.Δ. =	780.646759
519.5	519.5			
211		32.261220 x	1.243100 =	40.103923
116		6.670000 x	20.419486 =	136.197972
115		6.670000 x	21.778427 =	145.262108
519.5M		.800000 x	399.800000 =	319.840000
211		322.612206 x	1.243100 =	401.039233
				-----
			H.Δ. =	1,042.443236
519.6	519.6			
211		16.658521 x	1.243100 =	20.708207
211		166.585213 x	1.243100 =	207.082078
115		6.670000 x	21.778427 =	145.262108
116		6.670000 x	20.419486 =	136.197972
519.6M		.800000 x	259.330000 =	207.464000
				-----
			H.Δ. =	716.714365
521	521			
521.1		.250000 x	330.022376 =	82.505594
521.4		.150000 x	387.043266 =	58.056490
521.5		.150000 x	397.547266 =	59.632090
521.2		.250000 x	337.426179 =	84.356545
521.3		.200000 x	323.983898 =	64.796780
				-----
			H.Δ. =	349.347498
521.1	521.1			
211		7.471969 x	1.243100 =	9.288405
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
521.1M		.800000 x	73.160000 =	58.528000
211		74.719694 x	1.243100 =	92.884052
				-----
			H.Δ. =	330.022376

521.2	521.2			
211		80.134165 x	1.243100 =	99.614781
114		6.670000 x	23.886192 =	159.320901
521.2M		.800000 x	73.160000 =	58.528000
118		1.000000 x	10.001019 =	10.001019
211		8.013417 x	1.243100 =	9.961479
		-----		
			H.Δ. =	337.426179
521.3	521.3			
211		76.885483 x	1.243100 =	95.576344
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
521.3M		.800000 x	61.910000 =	49.528000
211		7.688548 x	1.243100 =	9.557634
		-----		
			H.Δ. =	323.983898
521.4	521.4			
211		11.586967 x	1.243100 =	14.403759
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
521.4M		.800000 x	74.100000 =	59.280000
211		115.869671 x	1.243100 =	144.037588
		-----		
			H.Δ. =	387.043266
521.5	521.5			
211		115.869671 x	1.243100 =	144.037588
211		11.586967 x	1.243100 =	14.403759
521.5M		.800000 x	87.230000 =	69.784000
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	397.547266
522	522			
522.6		.500000 x	492.075058 =	246.037529
522.7		.500000 x	486.152016 =	243.076008
		-----		
			H.Δ. =	489.113537
522.6	522.6			
211		17.109727 x	1.243100 =	21.269102
521.6M		.800000 x	98.490000 =	78.792000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
211		171.097271 x	1.243100 =	212.691018
		-----		
			H.Δ. =	492.075058

522.7	522.7			
211		16.676569 x	1.243100 =	20.730643
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
521.7M		.800000 x	98.490000 =	78.792000
211		166.765694 x	1.243100 =	207.306434
		-----		
			H.Δ. =	486.152016
523	523			
523.1		1.000000 x	365.895178 =	365.895178
		-----		
			H.Δ. =	365.895178
523.1	523.1			
211		54.144706 x	1.243100 =	67.307284
523.1M		.800000 x	93.690000 =	74.952000
117		6.670000 x	16.777917 =	111.908706
111		6.670000 x	15.741598 =	104.996459
211		5.414471 x	1.243100 =	6.730729
		-----		
			H.Δ. =	365.895178
525	525			
525.1		1.000000 x	256.385599 =	256.385599
		-----		
			H.Δ. =	256.385599
525.1	525.1			
211		4.512059 x	1.243100 =	5.608941
118		6.670000 x	10.001019 =	66.706797
111		6.670000 x	15.741598 =	104.996459
525.1M		.800000 x	28.730000 =	22.984000
211		45.120588 x	1.243100 =	56.089403
		-----		
			H.Δ. =	256.385599
526	526			
526.1		1.000000 x	599.986818 =	599.986818
		-----		
			H.Δ. =	599.986818
526.1	526.1			
211		243.651176 x	1.243100 =	302.882777
118		3.000000 x	10.001019 =	30.003057
117		6.670000 x	16.777917 =	111.908706
526.1M		.800000 x	156.130000 =	124.904000
211		24.365118 x	1.243100 =	30.288278
		-----		
			H.Δ. =	599.986818

527	527			
527.1		.400000 x	2,198.768364 =	879.507346
527.2		.600000 x	3,216.604391 =	1,929.962635
-----				
			H.Δ. =	2,809.469980
527.1	527.1			
211		433.157646 x	1.243100 =	538.458270
114		16.680000 x	23.886192 =	398.421683
118		6.670000 x	10.001019 =	66.706797
211		43.315765 x	1.243100 =	53.845827
112		6.670000 x	17.312112 =	115.471787
527.1M		.800000 x	1,282.330000 =	1,025.864000
-----				
			H.Δ. =	2,198.768364
527.2	527.2			
211		54.144706 x	1.243100 =	67.307284
118		6.670000 x	10.001019 =	66.706797
114		16.680000 x	23.886192 =	398.421683
112		6.670000 x	17.312112 =	115.471787
211		541.447060 x	1.243100 =	673.072840
527.2M		.800000 x	2,369.530000 =	1,895.624000
-----				
			H.Δ. =	3,216.604391
528	528			
528.1		.250000 x	815.360356 =	203.840089
528.4		.250000 x	941.826302 =	235.456576
528.2		.250000 x	879.887428 =	219.971857
528.3		.250000 x	867.547760 =	216.886940
-----				
			H.Δ. =	876.155462
528.1	528.1			
211		7.941224 x	1.243100 =	9.871736
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
112		13.340000 x	17.312112 =	230.943574
528.1M		.800000 x	312.250000 =	249.800000
211		79.412235 x	1.243100 =	98.717349
-----				
			H.Δ. =	815.360356

528.2	528.2			
211		10.467976 x	1.243100 =	13.012741
211		104.679765 x	1.243100 =	130.127416
528.2M		.800000 x	349.720000 =	279.776000
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
112		13.340000 x	17.312112 =	230.943574
		-----		
			H.Δ. =	879.887428
528.3	528.3			
211		95.655647 x	1.243100 =	118.909535
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
211		9.565565 x	1.243100 =	11.890954
112		13.340000 x	17.312112 =	230.943574
528.3M		.800000 x	349.720000 =	279.776000
		-----		
			H.Δ. =	867.547760
528.4	528.4			
211		135.361765 x	1.243100 =	168.268210
211		13.536176 x	1.243100 =	16.826820
112		13.340000 x	17.312112 =	230.943574
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
528.4M		.800000 x	374.700000 =	299.760000
		-----		
			H.Δ. =	941.826302
529	529			
529.1		1.000000 x	765.951336 =	765.951336
		-----		
			H.Δ. =	765.951336
529.1	529.1			
211		24.365118 x	1.243100 =	30.288278
117		6.670000 x	16.777917 =	111.908706
112		13.340000 x	17.312112 =	230.943574
529.1M		.800000 x	112.410000 =	89.928000
211		243.651176 x	1.243100 =	302.882777
		-----		
			H.Δ. =	765.951336

2730A	2730A			
234		48.000000 x	.847400 =	40.675200
513		.250000 x	243.483867 =	60.870967
511		.150000 x	394.191898 =	59.128785
517		1.000000 x	1,845.574410 =	1,845.574410
504		.400000 x	824.456869 =	329.782748
509		.400000 x	595.837395 =	238.334958
509		.200000 x	595.837395 =	119.167479
113		13.340000 x	20.419486 =	272.395943
112		6.670000 x	17.312112 =	115.471787
111		6.670000 x	15.741598 =	104.996459
251		.040000 x	290.000000 =	11.600000
235		24.000000 x	.632700 =	15.184800

-----  
 B.T = 3,213.183535

2730B	2730B			
234		1,000.000000 x	.847400 =	847.400000
113		140.000000 x	20.419486 =	2,858.728040
112		360.000000 x	17.312112 =	6,232.360320
506		2.500000 x	491.192938 =	1,227.982345
517		9.000000 x	1,845.574410 =	16,610.169690
515		7.000000 x	594.679541 =	4,162.756787
509		5.000000 x	595.837395 =	2,979.186975
509		2.209627 x	595.837395 =	1,316.578396
111		360.000000 x	15.741598 =	5,666.975280
252		2.000000 x	290.000000 =	580.000000
235		500.000000 x	.632700 =	316.350000
251		2.000000 x	290.000000 =	580.000000

-----  
 B.T = 43,378.487833

2730Γ	2730Γ			
222		350.000000 x	.116200 =	40.670000
625		.500000 x	16.622113 =	8.311057
630		.200000 x	.549800 =	.109960
623		.800000 x	15.093056 =	12.074445

-----  
 B.T = 61.165461

611	611			
111		1.400000 x	15.741598 =	22.038237

-----  
 B.T = 22.038237

612	612			
111		.250000 x	15.741598 =	3.935400
503		.000588 x	1,804.471720 =	1.061029
504		.000833 x	824.456869 =	.686773

-----  
 B.T = 5.683201

613	613			
111		.200000 x	15.741598 =	3.148320
518		.000500 x	2,548.197006 =	1.274099
504		.001000 x	824.456869 =	.824457
503		.000667 x	1,804.471720 =	1.203583
-----				
			B.T =	6.450458
614	614			
112		.080000 x	17.312112 =	1.384969
518		.002500 x	2,548.197006 =	6.370493
504		.001000 x	824.456869 =	.824457
509		.001950 x	595.837395 =	1.161883
503		.000909 x	1,804.471720 =	1.640265
-----				
			B.T =	11.382066
615	615			
112		.080000 x	17.312112 =	1.384969
518		.002500 x	2,548.197006 =	6.370493
504		.001000 x	824.456869 =	.824457
509		.001950 x	595.837395 =	1.161883
503		.000909 x	1,804.471720 =	1.640265
-----				
			B.T =	11.382066
616	616			
112		.080000 x	17.312112 =	1.384969
503		.000909 x	1,804.471720 =	1.640265
518		.002500 x	2,548.197006 =	6.370493
504		.001000 x	824.456869 =	.824457
509		.001950 x	595.837395 =	1.161883
-----				
			B.T =	11.382066
617	617			
111		.100000 x	15.741598 =	1.574160
503		.001000 x	1,804.471720 =	1.804472
518		.000625 x	2,548.197006 =	1.592623
504		.001000 x	824.456869 =	.824457
-----				
			B.T =	5.795712
621	621			
213		1.000000 x	1.949500 =	1.949500
519		.002500 x	804.361207 =	2.010903
111		.650000 x	15.741598 =	10.232039
116		.060000 x	20.419486 =	1.225169
-----				
			B.T =	15.417611

622	622			
213		1.000000 x	1.949500 =	1.949500
518		.001515 x	2,548.197006 =	3.860518
504		.001111 x	824.456869 =	.915972
519		.002500 x	804.361207 =	2.010903
509		.001950 x	595.837395 =	1.161883
503		.000909 x	1,804.471720 =	1.640265
116		.100000 x	20.419486 =	2.041949
112		.100000 x	17.312112 =	1.731211
			B.T =	15.312201
623	623			
213		1.000000 x	1.949500 =	1.949500
112		.100000 x	17.312112 =	1.731211
503		.000909 x	1,804.471720 =	1.640265
519		.002500 x	804.361207 =	2.010903
518		.001429 x	2,548.197006 =	3.641374
504		.001111 x	824.456869 =	.915972
509		.001950 x	595.837395 =	1.161883
116		.100000 x	20.419486 =	2.041949
			B.T =	15.093056
624	624			
213		1.000000 x	1.949500 =	1.949500
116		.100000 x	20.419486 =	2.041949
518		.001515 x	2,548.197006 =	3.860518
504		.001111 x	824.456869 =	.915972
519		.002500 x	804.361207 =	2.010903
509		.001950 x	595.837395 =	1.161883
503		.000909 x	1,804.471720 =	1.640265
112		.100000 x	17.312112 =	1.731211
			B.T =	15.312201
625	625			
213		1.000000 x	1.949500 =	1.949500
518		.002119 x	2,548.197006 =	5.399629
504		.000833 x	824.456869 =	.686773
519		.002500 x	804.361207 =	2.010903
509		.001950 x	595.837395 =	1.161883
503		.000909 x	1,804.471720 =	1.640265
116		.100000 x	20.419486 =	2.041949
112		.100000 x	17.312112 =	1.731211
			B.T =	16.622113
626	626			
509		.001786 x	595.837395 =	1.064166
504		.002000 x	824.456869 =	1.648914
			B.T =	2.713079

630	630			
512		.004255 x	129.212587 =	.549800
-----				
			B.T =	.549800
641	641			
231		.200000 x	.895000 =	.179000
111		.200000 x	15.741598 =	3.148320
113		.150000 x	20.419486 =	3.062923
252		.002500 x	290.000000 =	.725000
251		.001500 x	290.000000 =	.435000
-----				
			B.T =	7.550243
642	642			
231		.300000 x	.895000 =	.268500
113		.250000 x	20.419486 =	5.104872
111		.250000 x	15.741598 =	3.935400
252		.005000 x	290.000000 =	1.450000
251		.003000 x	290.000000 =	.870000
-----				
			B.T =	11.628771
651	651			
221		150.000000 x	.099900 =	14.985000
111		1.500000 x	15.741598 =	23.612397
112		.500000 x	17.312112 =	8.656056
625		1.000000 x	16.622113 =	16.622113
511		.040000 x	394.191898 =	15.767676
509		.002166 x	595.837395 =	1.290584
509		.007516 x	595.837395 =	4.478314
630		.600000 x	.549800 =	.329880
224		120.000000 x	.070000 =	8.400000
-----				
			B.T =	94.142020
652	652			
221		650.000000 x	.099900 =	64.935000
111		1.500000 x	15.741598 =	23.612397
511		.040000 x	394.191898 =	15.767676
509		.002166 x	595.837395 =	1.290584
509		.007516 x	595.837395 =	4.478314
630		.320000 x	.549800 =	.175936
625		1.000000 x	16.622113 =	16.622113
112		.500000 x	17.312112 =	8.656056
-----				
			B.T =	135.538076

661	661			
353		.160000 x	3.630000 =	.580800
354		.220000 x	4.020000 =	.884400
113		1.100000 x	20.419486 =	22.461435
355		.250000 x	.121800 =	.030450
-----				
			B.T =	23.957085
671	671			
215		.562500 x	1.081100 =	.608119
525		.000067 x	256.385599 =	.017178
111		.002000 x	15.741598 =	.031483
321		.550000 x	.596000 =	.327800
-----				
			B.T =	.984580
671.1	671.1			
215		.562500 x	1.081100 =	.608119
525		.000067 x	256.385599 =	.017178
111		.002000 x	15.741598 =	.031483
-----				
			B.T =	.656780
672	672			
215		.075000 x	1.081100 =	.081083
321		.940000 x	.596000 =	.560240
525		.000067 x	256.385599 =	.017178
111		.002000 x	15.741598 =	.031483
-----				
			B.T =	.689984
672.1	672.1			
215		.075000 x	1.081100 =	.081083
525		.000067 x	256.385599 =	.017178
111		.002000 x	15.741598 =	.031483
-----				
			B.T =	.129744
4311A	4311A			
321		80.000000 x	.596000 =	47.680000
616		.200000 x	11.382066 =	2.276413
615		.370000 x	11.382066 =	4.211364
527		.001786 x	2,809.469980 =	5.017713
504		.001786 x	824.456869 =	1.472480
626		.030000 x	2.713079 =	.081392
625		.500000 x	16.622113 =	8.311057
-----				
			B.T =	69.050420

4311A.1	4311A.1			
625		.500000 x	16.622113 =	8.311057
626		.030000 x	2.713079 =	.081392
504		.001786 x	824.456869 =	1.472480
527		.001786 x	2,809.469980 =	5.017713
616		.200000 x	11.382066 =	2.276413
615		.370000 x	11.382066 =	4.211364
-----				
			B.T =	21.370420
4311B	4311B			
321		80.000000 x	.596000 =	47.680000
626		.030000 x	2.713079 =	.081392
625		.500000 x	16.622113 =	8.311057
623		.370000 x	15.093056 =	5.584431
527		.001786 x	2,809.469980 =	5.017713
504		.001786 x	824.456869 =	1.472480
624		.200000 x	15.312201 =	3.062440
-----				
			B.T =	71.209513
4311B.1	4311B.1			
623		.370000 x	15.093056 =	5.584431
625		.500000 x	16.622113 =	8.311057
527		.001786 x	2,809.469980 =	5.017713
504		.001786 x	824.456869 =	1.472480
626		.030000 x	2.713079 =	.081392
624		.200000 x	15.312201 =	3.062440
-----				
			B.T =	23.529513
4312	4312			
509		.001622 x	595.837395 =	.966448
504		.001000 x	824.456869 =	.824457
-----				
			B.T =	1.790905
4411A	4411A			
321		80.000000 x	.596000 =	47.680000
616		.200000 x	11.382066 =	2.276413
615		.370000 x	11.382066 =	4.211364
626		.030000 x	2.713079 =	.081392
625		.500000 x	16.622113 =	8.311057
504		.001786 x	824.456869 =	1.472480
527		.001786 x	2,809.469980 =	5.017713
-----				
			B.T =	69.050420

4411A.1	4411A.1			
625		.500000 x	16.622113 =	8.311057
626		.030000 x	2.713079 =	.081392
527		.001786 x	2,809.469980 =	5.017713
616		.200000 x	11.382066 =	2.276413
615		.370000 x	11.382066 =	4.211364
504		.001786 x	824.456869 =	1.472480
-----				
			B.T =	21.370420
4411B	4411B			
321		80.000000 x	.596000 =	47.680000
527		.001786 x	2,809.469980 =	5.017713
504		.001786 x	824.456869 =	1.472480
625		.500000 x	16.622113 =	8.311057
623		.370000 x	15.093056 =	5.584431
624		.200000 x	15.312201 =	3.062440
626		.030000 x	2.713079 =	.081392
-----				
			B.T =	71.209513
4411B.1	4411B.1			
623		.370000 x	15.093056 =	5.584431
624		.200000 x	15.312201 =	3.062440
626		.030000 x	2.713079 =	.081392
625		.500000 x	16.622113 =	8.311057
527		.001786 x	2,809.469980 =	5.017713
504		.001786 x	824.456869 =	1.472480
-----				
			B.T =	23.529513
4412	4412			
509		.001622 x	595.837395 =	.966448
504		.001000 x	824.456869 =	.824457
-----				
			B.T =	1.790905
4511A	4511A			
321		90.000000 x	.596000 =	53.640000
616		.300000 x	11.382066 =	3.414620
615		.370000 x	11.382066 =	4.211364
527		.001786 x	2,809.469980 =	5.017713
504		.001786 x	824.456869 =	1.472480
626		.050000 x	2.713079 =	.135654
625		.450000 x	16.622113 =	7.479951
-----				
			B.T =	75.371782

4511A.1	4511A.1			
625		.450000 x	16.622113 =	7.479951
626		.050000 x	2.713079 =	.135654
504		.001786 x	824.456869 =	1.472480
527		.001786 x	2,809.469980 =	5.017713
616		.300000 x	11.382066 =	3.414620
615		.370000 x	11.382066 =	4.211364
			B.T =	21.731782
4511B	4511B			
321		90.000000 x	.596000 =	53.640000
625		.450000 x	16.622113 =	7.479951
623		.370000 x	15.093056 =	5.584431
527		.001786 x	2,809.469980 =	5.017713
504		.001786 x	824.456869 =	1.472480
626		.050000 x	2.713079 =	.135654
624		.300000 x	15.312201 =	4.593660
			B.T =	77.923889
4511B.1	4511B.1			
623		.370000 x	15.093056 =	5.584431
527		.001786 x	2,809.469980 =	5.017713
504		.001786 x	824.456869 =	1.472480
626		.050000 x	2.713079 =	.135654
625		.450000 x	16.622113 =	7.479951
624		.300000 x	15.312201 =	4.593660
			B.T =	24.283889
4512	4512			
509		.001622 x	595.837395 =	.966448
504		.001000 x	824.456869 =	.824457
			B.T =	1.790905
1110	1110			
503		.000455 x	1,804.471720 =	.821035
501		.000250 x	656.473521 =	.164118
			T.E =	.985153
1121	1121			
112		.005000 x	17.312112 =	.086561
501		.000083 x	656.473521 =	.054487
503		.000714 x	1,804.471720 =	1.288393
			T.E =	1.429441

1122	1122			
112		.005000 x	17.312112 =	.086561
509		.002000 x	595.837395 =	1.191675
507		.000385 x	777.415012 =	.299305
501		.000080 x	656.473521 =	.052518
505		.000316 x	1,248.731860 =	.394599
503		.000100 x	1,804.471720 =	.180447
		-----		
			T.E =	2.205104
1123.A	1123.A			
112		.005000 x	17.312112 =	.086561
503		.000500 x	1,804.471720 =	.902236
509		.001429 x	595.837395 =	.851452
507		.000769 x	777.415012 =	.597832
501		.000080 x	656.473521 =	.052518
		-----		
			T.E =	2.490598
1123.B	1123.B			
509		.000870 x	595.837395 =	.518379
		-----		
			T.E =	.518379
1131	1131			
213		1.000000 x	1.949500 =	1.949500
519		.000952 x	804.361207 =	.765752
112		.030000 x	17.312112 =	.519363
503		.000909 x	1,804.471720 =	1.640265
		-----		
			T.E =	4.874880
1132	1132			
213		1.000000 x	1.949500 =	1.949500
504		.001000 x	824.456869 =	.824457
503		.000909 x	1,804.471720 =	1.640265
112		.120000 x	17.312112 =	2.077453
519		.000952 x	804.361207 =	.765752
509		.002000 x	595.837395 =	1.191675
		-----		
			T.E =	8.449102
1133.A	1133.A			
213		1.000000 x	1.949500 =	1.949500
112		.120000 x	17.312112 =	2.077453
504		.001000 x	824.456869 =	.824457
519		.000952 x	804.361207 =	.765752
509		.001176 x	595.837395 =	.700705
503		.000909 x	1,804.471720 =	1.640265
		-----		
			T.E =	7.958132

1133.B	1133.B			
509		.000870 x	595.837395 =	.518379
		-----		
			T.E =	.518379
1140	1140			
112		.006000 x	17.312112 =	.103873
522		.000133 x	489.113537 =	.065052
501		.000050 x	656.473521 =	.032824
		-----		
			T.E =	.201748
1211	1211			
112		.200000 x	17.312112 =	3.462422
501		.001538 x	656.473521 =	1.009656
507		.001538 x	777.415012 =	1.195664
		-----		
			T.E =	5.667743
1212	1212			
112		.200000 x	17.312112 =	3.462422
507		.001538 x	777.415012 =	1.195664
501		.001538 x	656.473521 =	1.009656
509		.002298 x	595.837395 =	1.369234
		-----		
			T.E =	7.036977
1220	1220			
213		1.000000 x	1.949500 =	1.949500
116		.060000 x	20.419486 =	1.225169
519		.002222 x	804.361207 =	1.787291
111		.500000 x	15.741598 =	7.870799
112		.060000 x	17.312112 =	1.038727
		-----		
			T.E =	13.871485
1310	1310			
112		.070000 x	17.312112 =	1.211848
501		.000385 x	656.473521 =	.252742
		-----		
			T.E =	1.464590
1320	1320			
112		1.500000 x	17.312112 =	25.968168
		-----		
			T.E =	25.968168

1410	1410			
112		.005000 x	17.312112 =	.086561
501		.000083 x	656.473521 =	.054487
503		.000833 x	1,804.471720 =	1.503125
-----				
			T.E =	1.644173
1420	1420			
112		.006000 x	17.312112 =	.103873
509		.001826 x	595.837395 =	1.087999
503		.000208 x	1,804.471720 =	.375330
501		.000050 x	656.473521 =	.032824
507		.000385 x	777.415012 =	.299305
505		.000316 x	1,248.731860 =	.394599
-----				
			T.E =	2.293930
1510	1510			
112		.007000 x	17.312112 =	.121185
509		.001429 x	595.837395 =	.851452
504		.000714 x	824.456869 =	.588662
503		.000385 x	1,804.471720 =	.694722
-----				
			T.E =	2.256020
1520	1520			
509		.000833 x	595.837395 =	.496333
-----				
			T.E =	.496333
1530	1530			
630		.150000 x	.549800 =	.082470
502		.000208 x	1,053.784794 =	.219187
501		.000250 x	656.473521 =	.164118
509		.000413 x	595.837395 =	.246081
522		.000556 x	489.113537 =	.271947
-----				
			T.E =	.983804
1610	1610			
111		.040000 x	15.741598 =	.629664
503		.000111 x	1,804.471720 =	.200296
507		.000118 x	777.415012 =	.091735
1122		.200000 x	2.205104 =	.441021
501		.000050 x	656.473521 =	.032824
-----				
			T.E =	1.395540

1620	1620			
112		.200000 x	17.312112 =	3.462422
1122		1.000000 x	2.205104 =	2.205104
501		.000714 x	656.473521 =	.468722
-----				
			T.E =	6.136248
2111	2111			
112		.010000 x	17.312112 =	.173121
503		.001053 x	1,804.471720 =	1.900109
507		.000667 x	777.415012 =	.518536
501		.000500 x	656.473521 =	.328237
509		.002124 x	595.837395 =	1.265559
-----				
			T.E =	4.185561
2112	2112			
213		1.000000 x	1.949500 =	1.949500
112		.250000 x	17.312112 =	4.328028
507		.000667 x	777.415012 =	.518536
519		.002041 x	804.361207 =	1.641701
509		.002124 x	595.837395 =	1.265559
503		.001613 x	1,804.471720 =	2.910613
116		.060000 x	20.419486 =	1.225169
-----				
			T.E =	13.839106
2151	2151			
213		.300000 x	1.949500 =	.584850
112		.100000 x	17.312112 =	1.731211
112		.200000 x	17.312112 =	3.462422
113		.030000 x	20.419486 =	.612585
112		.100000 x	17.312112 =	1.731211
507		.003333 x	777.415012 =	2.591124
519		.001200 x	804.361207 =	.965233
509		.002124 x	595.837395 =	1.265559
-----				
			T.E =	12.944196
2152	2152			
112		.200000 x	17.312112 =	3.462422
507		.006667 x	777.415012 =	5.183026
509		.003196 x	595.837395 =	1.904296
112		.100000 x	17.312112 =	1.731211
-----				
			T.E =	12.280956

2211	2211			
244		1.000000 x	2.700000 =	2.700000
515		.000004 x	594.679541 =	.002379
515		.000004 x	594.679541 =	.002379
509		.000051 x	595.837395 =	.030388
112		.003000 x	17.312112 =	.051936
112		.002000 x	17.312112 =	.034624
		-----		
			T.E =	2.821706
2212	2212			
244		.125000 x	2.700000 =	.337500
112		.007000 x	17.312112 =	.121185
515		.000008 x	594.679541 =	.004757
509		.000051 x	595.837395 =	.030388
		-----		
			T.E =	.493830
2213	2213			
236		3.000000 x	.624500 =	1.873500
517		.016667 x	1,845.574410 =	30.760189
515		.016667 x	594.679541 =	9.911524
113		.300000 x	20.419486 =	6.125846
111		.300000 x	15.741598 =	4.722479
		-----		
			T.E =	53.393538
2214	2214			
111		.170000 x	15.741598 =	2.676072
515		.016667 x	594.679541 =	9.911524
113		.110000 x	20.419486 =	2.246143
111		.200000 x	15.741598 =	3.148320
113		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	22.065956
2251	2251			
111		.450000 x	15.741598 =	7.083719
112		.450000 x	17.312112 =	7.790450
509		.007516 x	595.837395 =	4.478314
621		1.050000 x	15.417611 =	16.188492
		-----		
			T.E =	35.540975
2252	2252			
111		1.250000 x	15.741598 =	19.676998
621		1.050000 x	15.417611 =	16.188492
509		.007516 x	595.837395 =	4.478314
113		1.250000 x	20.419486 =	25.524358
		-----		
			T.E =	65.868160

2253	2253			
111		1.500000 x	15.741598 =	23.612397
621		1.050000 x	15.417611 =	16.188492
652		.020000 x	135.538076 =	2.710762
509		.007891 x	595.837395 =	4.701753
651		.250000 x	94.142020 =	23.535505
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422
			T.E =	125.260045
2254	2254			
111		.750000 x	15.741598 =	11.806199
652		.100000 x	135.538076 =	13.553808
113		1.450000 x	20.419486 =	29.608255
509		.002630 x	595.837395 =	1.567052
621		.350000 x	15.417611 =	5.396164
			T.E =	61.931477
2311	2311			
243		1.020000 x	2.400000 =	2.448000
243		.080000 x	2.400000 =	.192000
			T.E =	2.640000
2312	2312			
112		.080000 x	17.312112 =	1.384969
113		.080000 x	20.419486 =	1.633559
			T.E =	3.018528
2313	2313			
111		.400000 x	15.741598 =	6.296639
509		.003326 x	595.837395 =	1.981755
611		1.050000 x	22.038237 =	23.140149
112		.400000 x	17.312112 =	6.924845
			T.E =	38.343388
2350	2350			
112		.100000 x	17.312112 =	1.731211
652		.022000 x	135.538076 =	2.981838
113		.250000 x	20.419486 =	5.104872
			T.E =	9.817920
2411	2411			
327		.500000 x	.540000 =	.270000
113		.180000 x	20.419486 =	3.675507
			T.E =	3.945507

2412	2412			
328		2.200000 x	1.840000 =	4.048000
111		.150000 x	15.741598 =	2.361240
329		2.000000 x	.730000 =	1.460000
2350		1.000000 x	9.817920 =	9.817920
113		.300000 x	20.419486 =	6.125846
-----				
			T.E =	23.813006
2511	2511			
221		200.000000 x	.099900 =	19.980000
623		.800000 x	15.093056 =	12.074445
625		.500000 x	16.622113 =	8.311057
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.016667 x	595.837395 =	9.930822
509		.003758 x	595.837395 =	2.239157
509		.001444 x	595.837395 =	.860389
509		.006012 x	595.837395 =	3.582174
630		.250000 x	.549800 =	.137450
112		.400000 x	17.312112 =	6.924845
113		.250000 x	20.419486 =	5.104872
-----				
			T.E =	72.178372
2512	2512			
221		250.000000 x	.099900 =	24.975000
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174
509		.003758 x	595.837395 =	2.239157
509		.001444 x	595.837395 =	.860389
630		.250000 x	.549800 =	.137450
641		2.000000 x	7.550243 =	15.100486
625		.500000 x	16.622113 =	8.311057
509		.018182 x	595.837395 =	10.833516
623		.800000 x	15.093056 =	12.074445
112		.500000 x	17.312112 =	8.656056
113		.500000 x	20.419486 =	10.209743
-----				
			T.E =	100.012635

2521	2521			
221		50.000000 x	.099900 =	4.995000
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.003758 x	595.837395 =	2.239157
509		.001444 x	595.837395 =	.860389
509		.018182 x	595.837395 =	10.833516
509		.006012 x	595.837395 =	3.582174
641		2.000000 x	7.550243 =	15.100486
630		.250000 x	.549800 =	.137450
625		.500000 x	16.622113 =	8.311057
623		.800000 x	15.093056 =	12.074445
113		.500000 x	20.419486 =	10.209743
112		.500000 x	17.312112 =	8.656056
221		250.000000 x	.099900 =	24.975000

T.E = 105.007635

2522	2522			
221		300.000000 x	.099900 =	29.970000
113		.800000 x	20.419486 =	16.335589
625		.500000 x	16.622113 =	8.311057
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174
509		.003758 x	595.837395 =	2.239157
509		.001444 x	595.837395 =	.860389
509		.018182 x	595.837395 =	10.833516
641		3.000000 x	7.550243 =	22.650729
630		.250000 x	.549800 =	.137450
623		.800000 x	15.093056 =	12.074445
112		.600000 x	17.312112 =	10.387267

T.E = 120.414935

2523	2523			
221		300.000000 x	.099900 =	29.970000
641		3.000000 x	7.550243 =	22.650729
630		.250000 x	.549800 =	.137450
625		.500000 x	16.622113 =	8.311057
509		.001444 x	595.837395 =	.860389
509		.003758 x	595.837395 =	2.239157
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.018182 x	595.837395 =	10.833516
509		.006012 x	595.837395 =	3.582174
623		.800000 x	15.093056 =	12.074445
113		1.050000 x	20.419486 =	21.440460
112		.750000 x	17.312112 =	12.984084

T.E = 128.116623

2524	2524			
221		300.000000 x	.099900 =	29.970000
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174
509		.003758 x	595.837395 =	2.239157
509		.001444 x	595.837395 =	.860389
509		.018182 x	595.837395 =	10.833516
641		1.300000 x	7.550243 =	9.815316
630		.250000 x	.549800 =	.137450
625		.500000 x	16.622113 =	8.311057
623		.800000 x	15.093056 =	12.074445
113		.800000 x	20.419486 =	16.335589
112		1.200000 x	17.312112 =	20.774534

-----  
 T.E = 117.966789

2531	2531			
222		300.000000 x	.116200 =	34.860000
112		1.300000 x	17.312112 =	22.505746
113		.900000 x	20.419486 =	18.377537
630		.250000 x	.549800 =	.137450
509		.018182 x	595.837395 =	10.833516
509		.003758 x	595.837395 =	2.239157
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.001444 x	595.837395 =	.860389
509		.006012 x	595.837395 =	3.582174
641		1.300000 x	7.550243 =	9.815316
625		.500000 x	16.622113 =	8.311057
623		.800000 x	15.093056 =	12.074445

-----  
 T.E = 126.629949

2532	2532			
222		300.000000 x	.116200 =	34.860000
509		.006012 x	595.837395 =	3.582174
509		.001444 x	595.837395 =	.860389
509		.018182 x	595.837395 =	10.833516
509		.003758 x	595.837395 =	2.239157
641		4.000000 x	7.550243 =	30.200972
630		.250000 x	.549800 =	.137450
625		.500000 x	16.622113 =	8.311057
112		1.600000 x	17.312112 =	27.699379
623		.800000 x	15.093056 =	12.074445
113		.900000 x	20.419486 =	18.377537
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354

-----  
 T.E = 152.209238

2533	2533			
222		300.000000 x	.116200 =	34.860000
112		1.800000 x	17.312112 =	31.161802
623		.800000 x	15.093056 =	12.074445
630		.250000 x	.549800 =	.137450
509		.001444 x	595.837395 =	.860389
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174
509		.003758 x	595.837395 =	2.239157
509		.018182 x	595.837395 =	10.833516
641		8.000000 x	7.550243 =	60.401944
625		.500000 x	16.622113 =	8.311057
113		1.200000 x	20.419486 =	24.503383

T.E = 191.998479

2541	2541			
222		300.000000 x	.116200 =	34.860000
509		.001444 x	595.837395 =	.860389
509		.018182 x	595.837395 =	10.833516
509		.003758 x	595.837395 =	2.239157
641		4.500000 x	7.550243 =	33.976094
630		.250000 x	.549800 =	.137450
625		.500000 x	16.622113 =	8.311057
623		.800000 x	15.093056 =	12.074445
113		1.200000 x	20.419486 =	24.503383
112		1.600000 x	17.312112 =	27.699379
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174

T.E = 162.110206

2542	2542			
222		300.000000 x	.116200 =	34.860000
112		1.650000 x	17.312112 =	28.564985
623		.800000 x	15.093056 =	12.074445
509		.018182 x	595.837395 =	10.833516
509		.003758 x	595.837395 =	2.239157
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174
509		.001444 x	595.837395 =	.860389
630		.250000 x	.549800 =	.137450
642		4.500000 x	11.628771 =	52.329470
625		.500000 x	16.622113 =	8.311057
113		1.250000 x	20.419486 =	25.524358

T.E = 182.350162

2543	2543			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174
509		.003758 x	595.837395 =	2.239157
509		.001444 x	595.837395 =	.860389
509		.018182 x	595.837395 =	10.833516
641		5.000000 x	7.550243 =	37.751215
630		.250000 x	.549800 =	.137450
625		.500000 x	16.622113 =	8.311057
623		.800000 x	15.093056 =	12.074445
112		1.550000 x	17.312112 =	26.833774
113		.500000 x	20.419486 =	10.209743
113		1.250000 x	20.419486 =	25.524358

-----  
 T.E = 176.250439

2544	2544			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174
509		.001444 x	595.837395 =	.860389
509		.018182 x	595.837395 =	10.833516
509		.003758 x	595.837395 =	2.239157
113		1.250000 x	20.419486 =	25.524358
112		1.650000 x	17.312112 =	28.564985
625		.500000 x	16.622113 =	8.311057
642		5.000000 x	11.628771 =	58.143855
630		.250000 x	.549800 =	.137450
623		.800000 x	15.093056 =	12.074445
113		.700000 x	20.419486 =	14.293640

-----  
 T.E = 202.458187

2545	2545			
222		300.000000 x	.116200 =	34.860000
509		.001444 x	595.837395 =	.860389
509		.018182 x	595.837395 =	10.833516
509		.003758 x	595.837395 =	2.239157
641		6.000000 x	7.550243 =	45.301458
630		.250000 x	.549800 =	.137450
625		.500000 x	16.622113 =	8.311057
623		.800000 x	15.093056 =	12.074445
113		1.900000 x	20.419486 =	38.797023
112		1.650000 x	17.312112 =	28.564985
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174

-----  
 T.E = 188.594816

2546	2546			
222		300.000000 x	.116200 =	34.860000
112		1.850000 x	17.312112 =	32.027407
113		1.900000 x	20.419486 =	38.797023
509		.018182 x	595.837395 =	10.833516
509		.003758 x	595.837395 =	2.239157
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174
509		.001444 x	595.837395 =	.860389
630		.250000 x	.549800 =	.137450
641		6.000000 x	7.550243 =	45.301458
625		.500000 x	16.622113 =	8.311057
623		.800000 x	15.093056 =	12.074445

-----  
 T.E = 192.057238

2547	2547			
222		300.000000 x	.116200 =	34.860000
509		.001444 x	595.837395 =	.860389
509		.018182 x	595.837395 =	10.833516
509		.003758 x	595.837395 =	2.239157
641		5.000000 x	7.550243 =	37.751215
630		.250000 x	.549800 =	.137450
625		.500000 x	16.622113 =	8.311057
112		1.550000 x	17.312112 =	26.833774
623		.800000 x	15.093056 =	12.074445
113		1.900000 x	20.419486 =	38.797023
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174

-----  
 T.E = 179.313362

2548	2548			
222		300.000000 x	.116200 =	34.860000
112		1.950000 x	17.312112 =	33.758618
623		.800000 x	15.093056 =	12.074445
509		.018182 x	595.837395 =	10.833516
509		.003758 x	595.837395 =	2.239157
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174
509		.001444 x	595.837395 =	.860389
630		.250000 x	.549800 =	.137450
641		5.000000 x	7.550243 =	37.751215
625		.500000 x	16.622113 =	8.311057
113		2.400000 x	20.419486 =	49.006766

-----  
 T.E = 196.447950

2551	2551			
222		360.000000 x	.116200 =	41.832000
514		.002857 x	731.819490 =	2.090808
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174
509		.003758 x	595.837395 =	2.239157
509		.001444 x	595.837395 =	.860389
509		.018182 x	595.837395 =	10.833516
641		4.500000 x	7.550243 =	33.976094
630		.250000 x	.549800 =	.137450
625		.500000 x	16.622113 =	8.311057
623		.800000 x	15.093056 =	12.074445
113		1.050000 x	20.419486 =	21.440460
112		1.550000 x	17.312112 =	26.833774

-----  
 T.E = 165.153677

2561	2561			
222		450.000000 x	.116200 =	52.290000
111		1.250000 x	15.741598 =	19.676998
112		1.800000 x	17.312112 =	31.161802
623		.800000 x	15.093056 =	12.074445
514		.003704 x	731.819490 =	2.710659
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174
509		.003758 x	595.837395 =	2.239157
509		.001444 x	595.837395 =	.860389
509		.018182 x	595.837395 =	10.833516
641		4.500000 x	7.550243 =	33.976094
630		.250000 x	.549800 =	.137450
625		.500000 x	16.622113 =	8.311057
113		2.800000 x	20.419486 =	57.174561

-----  
 T.E = 235.970654

2562	2562			
222		450.000000 x	.116200 =	52.290000
111		1.950000 x	15.741598 =	30.696116
514		.003704 x	731.819490 =	2.710659
504		.001143 x	824.456869 =	.942354
509		.003758 x	595.837395 =	2.239157
509		.001444 x	595.837395 =	.860389
509		.018182 x	595.837395 =	10.833516
509		.006012 x	595.837395 =	3.582174
642		4.500000 x	11.628771 =	52.329470
630		.250000 x	.549800 =	.137450
625		.500000 x	16.622113 =	8.311057
113		2.800000 x	20.419486 =	57.174561
623		.800000 x	15.093056 =	12.074445
112		1.800000 x	17.312112 =	31.161802

-----  
 T.E = 265.343149

2563	2563			
222		450.000000 x	.116200 =	52.290000
111		1.950000 x	15.741598 =	30.696116
514		.003704 x	731.819490 =	2.710659
504		.001143 x	824.456869 =	.942354
509		.003758 x	595.837395 =	2.239157
509		.018182 x	595.837395 =	10.833516
509		.001444 x	595.837395 =	.860389
509		.006012 x	595.837395 =	3.582174
641		5.000000 x	7.550243 =	37.751215
630		.250000 x	.549800 =	.137450
625		.500000 x	16.622113 =	8.311057
623		.800000 x	15.093056 =	12.074445
113		3.900000 x	20.419486 =	79.635995
113		.900000 x	20.419486 =	18.377537
112		1.800000 x	17.312112 =	31.161802
-----				

T.E = 291.603866

2564	2564			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	731.819490 =	2.710659
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174
509		.003758 x	595.837395 =	2.239157
509		.001444 x	595.837395 =	.860389
509		.018182 x	595.837395 =	10.833516
642		5.000000 x	11.628771 =	58.143855
630		.250000 x	.549800 =	.137450
625		.500000 x	16.622113 =	8.311057
623		.800000 x	15.093056 =	12.074445
113		.900000 x	20.419486 =	18.377537
112		1.800000 x	17.312112 =	31.161802
113		3.900000 x	20.419486 =	79.635995
111		1.950000 x	15.741598 =	30.696116
-----				

T.E = 311.996506

2565	2565			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	731.819490 =	2.710659
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174
509		.003758 x	595.837395 =	2.239157
509		.001444 x	595.837395 =	.860389
509		.018182 x	595.837395 =	10.833516
641		6.000000 x	7.550243 =	45.301458
630		.250000 x	.549800 =	.137450
625		.500000 x	16.622113 =	8.311057
623		.800000 x	15.093056 =	12.074445
113		4.700000 x	20.419486 =	95.971584
112		2.350000 x	17.312112 =	40.683463
111		2.350000 x	15.741598 =	36.992755
-----				

T.E = 312.930462

2566	2566			
222		450.000000 x	.116200 =	52.290000
630		.250000 x	.549800 =	.137450
514		.003704 x	731.819490 =	2.710659
504		.001143 x	824.456869 =	.942354
509		.006012 x	595.837395 =	3.582174
509		.003758 x	595.837395 =	2.239157
509		.001444 x	595.837395 =	.860389
509		.018182 x	595.837395 =	10.833516
642		6.000000 x	11.628771 =	69.772626
625		.500000 x	16.622113 =	8.311057
623		.800000 x	15.093056 =	12.074445
113		4.700000 x	20.419486 =	95.971584
112		2.350000 x	17.312112 =	40.683463
111		2.350000 x	15.741598 =	36.992755
-----				
			T.E =	337.401630
2611	2611			
233		1.050000 x	.558700 =	.586635
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.301317
2612	2612			
238		1.050000 x	.558700 =	.586635
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.301317
2620	2620			
239		1.010000 x	8.250000 =	8.332500
113		.080000 x	20.419486 =	1.633559
113		.080000 x	20.419486 =	1.633559
239		.303000 x	8.250000 =	2.499750
-----				
			T.E =	14.099368
2651	2651			
235		1.050000 x	.632700 =	.664335
113		.100000 x	20.419486 =	2.041949
-----				
			T.E =	2.706284
2652	2652			
235		1.050000 x	.632700 =	.664335
661		.050000 x	23.957085 =	1.197854
113		.120000 x	20.419486 =	2.450338
-----				
			T.E =	4.312528

2653	2653			
241		1.050000 x	7.750000 =	8.137500
661		.120000 x	23.957085 =	2.874850
113		.800000 x	20.419486 =	16.335589
		-----		
			T.E =	27.347939
2671	2671			
237		1.000000 x	1.218000 =	1.218000
113		.015000 x	20.419486 =	.306292
		-----		
			T.E =	1.524292
2672	2672			
235		1.050000 x	.632700 =	.664335
661		.050000 x	23.957085 =	1.197854
113		.120000 x	20.419486 =	2.450338
		-----		
			T.E =	4.312528
2711	2711			
2551		1.000000 x	165.153677 =	165.153677
		-----		
			T.E =	165.153677
2712	2712			
2611		1.000000 x	1.301317 =	1.301317
		-----		
			T.E =	1.301317
2713	2713			
237		1.000000 x	1.218000 =	1.218000
113		.070000 x	20.419486 =	1.429364
		-----		
			T.E =	2.647364
2714	2714			
112		1.900000 x	17.312112 =	32.893013
517		.015385 x	1,845.574410 =	28.394162
516		.015385 x	945.853143 =	14.551951
		-----		
			T.E =	75.839126
2731	2731			
2730A		.149925 x	3,213.183535 =	481.736541
2730B		.000667 x	43,378.487833 =	28.933451
2730Γ		1.000000 x	61.165461 =	61.165461
		-----		
			T.E =	571.835454

2732	2732			
2730Α		.179910 x	3,213.183535 =	578.083850
2730Β		.000667 x	43,378.487833 =	28.933451
2730Γ		1.000000 x	61.165461 =	61.165461
-----				
			T.E =	668.182762
2733	2733			
233		1.050000 x	.558700 =	.586635
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.301317
2734	2734			
238		1.050000 x	.558700 =	.586635
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.301317
2811	2811			
112		.170000 x	17.312112 =	2.943059
509		.002217 x	595.837395 =	1.320972
507		.001538 x	777.415012 =	1.195664
501		.000500 x	656.473521 =	.328237
-----				
			T.E =	5.787932
2815	2815			
111		.250000 x	15.741598 =	3.935400
509		.005261 x	595.837395 =	3.134701
112		.350000 x	17.312112 =	6.059239
623		.400000 x	15.093056 =	6.037222
509		.003006 x	595.837395 =	1.791087
625		.700000 x	16.622113 =	11.635479
-----				
			T.E =	32.593128
2861	2861			
221		6.000000 x	.099900 =	.599400
281		1.000000 x	21.300000 =	21.300000
113		.200000 x	20.419486 =	4.083897
111		.250000 x	15.741598 =	3.935400
-----				
			T.E =	29.918697
2862	2862			
221		8.000000 x	.099900 =	.799200
282		1.000000 x	30.000000 =	30.000000
113		.200000 x	20.419486 =	4.083897
111		.250000 x	15.741598 =	3.935400
-----				
			T.E =	38.818497

2863	2863			
221		8.000000 x	.099900 =	.799200
283		1.000000 x	36.300000 =	36.300000
113		.550000 x	20.419486 =	11.230717
111		.650000 x	15.741598 =	10.232039
		-----		
			T.E =	58.561956
2864	2864			
221		16.000000 x	.099900 =	1.598400
113		.550000 x	20.419486 =	11.230717
111		.700000 x	15.741598 =	11.019119
284		1.000000 x	75.400000 =	75.400000
		-----		
			T.E =	99.248236
2881	2881			
221		6.000000 x	.099900 =	.599400
261		1.000000 x	15.100000 =	15.100000
113		.200000 x	20.419486 =	4.083897
111		.250000 x	15.741598 =	3.935400
		-----		
			T.E =	23.718697
2882	2882			
221		8.000000 x	.099900 =	.799200
262		1.000000 x	26.300000 =	26.300000
113		.200000 x	20.419486 =	4.083897
111		.250000 x	15.741598 =	3.935400
		-----		
			T.E =	35.118497
2883	2883			
221		10.000000 x	.099900 =	.999000
113		.550000 x	20.419486 =	11.230717
111		.650000 x	15.741598 =	10.232039
263		1.000000 x	32.400000 =	32.400000
		-----		
			T.E =	54.861756
2884	2884			
221		16.000000 x	.099900 =	1.598400
264		1.000000 x	64.100000 =	64.100000
113		.550000 x	20.419486 =	11.230717
111		.700000 x	15.741598 =	11.019119
		-----		
			T.E =	87.948236

2885	2885			
221		20.000000 x	.099900 =	1.998000
265		1.000000 x	115.100000 =	115.100000
113		.750000 x	20.419486 =	15.314615
111		1.000000 x	15.741598 =	15.741598
		-----		
			T.E =	148.154213
2888	2888			
221		26.000000 x	.099900 =	2.597400
111		1.400000 x	15.741598 =	22.038237
113		1.100000 x	20.419486 =	22.461435
271		1.000000 x	206.300000 =	206.300000
		-----		
			T.E =	253.397072
2911	2911			
351		1.050000 x	770.000000 =	808.500000
113		5.000000 x	20.419486 =	102.097430
		-----		
			T.E =	910.597430
2912	2912			
352		1.050000 x	1,040.000000 =	1,092.000000
113		5.000000 x	20.419486 =	102.097430
		-----		
			T.E =	1,194.097430
2921	2921			
301		1.000000 x	3.860000 =	3.860000
2522		.005000 x	120.414935 =	.602075
111		.250000 x	15.741598 =	3.935400
652		.002000 x	135.538076 =	.271076
113		.250000 x	20.419486 =	5.104872
		-----		
			T.E =	13.773422
2922	2922			
302		1.020000 x	6.360000 =	6.487200
652		.015000 x	135.538076 =	2.033071
111		.350000 x	15.741598 =	5.509559
113		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	26.281522
2951	2951			
512A		.150000 x	109.903811 =	16.485572
		-----		
			T.E =	16.485572

2952	2952			
512B		.150000 x	158.175586 =	23.726338
				-----
			T.E =	23.726338
2953	2953			
513A		.150000 x	217.174985 =	32.576248
				-----
			T.E =	32.576248
2954	2954			
513B		.150000 x	276.551633 =	41.482745
				-----
			T.E =	41.482745
3111A	3111A			
112		.020000 x	17.312112 =	.346242
522		.000263 x	489.113537 =	.128637
509		.000072 x	595.837395 =	.042900
509		.000193 x	595.837395 =	.114997
630		.020000 x	.549800 =	.010996
501		.000182 x	656.473521 =	.119478
614		.135000 x	11.382066 =	1.536579
				-----
			T.E =	2.299829
3111B	3111B			
112		.020000 x	17.312112 =	.346242
622		.135000 x	15.312201 =	2.067147
509		.000193 x	595.837395 =	.114997
501		.000182 x	656.473521 =	.119478
509		.000072 x	595.837395 =	.042900
522		.000263 x	489.113537 =	.128637
630		.020000 x	.549800 =	.010996
				-----
			T.E =	2.830397
3112	3112			
509		.000094 x	595.837395 =	.056009
				-----
			T.E =	.056009
3121A	3121A			
112		.200000 x	17.312112 =	3.462422
501		.001818 x	656.473521 =	1.193469
614		1.350000 x	11.382066 =	15.365789
509		.000722 x	595.837395 =	.430195
509		.001929 x	595.837395 =	1.149370
522		.002632 x	489.113537 =	1.287347
630		.200000 x	.549800 =	.109960
				-----
			T.E =	22.998552

3121B	3121B			
112		.200000 x	17.312112 =	3.462422
622		1.350000 x	15.312201 =	20.671471
509		.000722 x	595.837395 =	.430195
509		.001929 x	595.837395 =	1.149370
501		.001818 x	656.473521 =	1.193469
522		.002632 x	489.113537 =	1.287347
630		.200000 x	.549800 =	.109960
-----				
			T.E =	28.304234
3122	3122			
509		.000940 x	595.837395 =	.560087
-----				
			T.E =	.560087
3211A	3211A			
112		.025000 x	17.312112 =	.432803
509		.000193 x	595.837395 =	.114997
501		.000182 x	656.473521 =	.119478
614		.135000 x	11.382066 =	1.536579
509		.000072 x	595.837395 =	.042900
630		.020000 x	.549800 =	.010996
522		.000263 x	489.113537 =	.128637
-----				
			T.E =	2.386390
3211B	3211B			
112		.025000 x	17.312112 =	.432803
622		.135000 x	15.312201 =	2.067147
501		.000182 x	656.473521 =	.119478
509		.000072 x	595.837395 =	.042900
509		.000193 x	595.837395 =	.114997
522		.000263 x	489.113537 =	.128637
630		.020000 x	.549800 =	.010996
-----				
			T.E =	2.916958
3212	3212			
509		.000141 x	595.837395 =	.084013
-----				
			T.E =	.084013

3221	3221			
622		.202500 x	15.312201 =	3.100721
509		.000250 x	595.837395 =	.148959
509		.000286 x	595.837395 =	.170409
501		.000250 x	656.473521 =	.164118
509		.000250 x	595.837395 =	.148959
509		.000469 x	595.837395 =	.279448
630		.100000 x	.549800 =	.054980
522		.000500 x	489.113537 =	.244557
			T.E =	4.312152
3222	3222			
221		1.000000 x	.099900 =	.099900
			T.E =	.099900
3223	3223			
509		.000141 x	595.837395 =	.084013
			T.E =	.084013
3231	3231			
112		.025000 x	17.312112 =	.432803
522		.000286 x	489.113537 =	.139886
501		.000213 x	656.473521 =	.139829
509		.000054 x	595.837395 =	.032175
630		.015000 x	.549800 =	.008247
			T.E =	.752940
3232A	3232A			
630		.200000 x	.549800 =	.109960
614		1.350000 x	11.382066 =	15.365789
509		.001929 x	595.837395 =	1.149370
			T.E =	16.625119
3232B	3232B			
622		1.350000 x	15.312201 =	20.671471
509		.001929 x	595.837395 =	1.149370
630		.200000 x	.549800 =	.109960
			T.E =	21.930802
3233	3233			
509		.000940 x	595.837395 =	.560087
			T.E =	.560087

3241A	3241A			
112		.025000 x	17.312112 =	.432803
509		.000193 x	595.837395 =	.114997
509		.000072 x	595.837395 =	.042900
501		.000213 x	656.473521 =	.139829
614		.135000 x	11.382066 =	1.536579
630		.020000 x	.549800 =	.010996
522		.000286 x	489.113537 =	.139886
-----				
			T.E =	2.417990
3241B	3241B			
112		.025000 x	17.312112 =	.432803
509		.000072 x	595.837395 =	.042900
501		.000213 x	656.473521 =	.139829
509		.000193 x	595.837395 =	.114997
622		.135000 x	15.312201 =	2.067147
522		.000286 x	489.113537 =	.139886
630		.020000 x	.549800 =	.010996
-----				
			T.E =	2.948558
3242	3242			
509		.000094 x	595.837395 =	.056009
-----				
			T.E =	.056009
3311A	3311A			
112		.025000 x	17.312112 =	.432803
501		.000213 x	656.473521 =	.139829
614		.135000 x	11.382066 =	1.536579
509		.000193 x	595.837395 =	.114997
509		.000072 x	595.837395 =	.042900
522		.000286 x	489.113537 =	.139886
630		.020000 x	.549800 =	.010996
-----				
			T.E =	2.417990
3311B	3311B			
112		.025000 x	17.312112 =	.432803
622		.135000 x	15.312201 =	2.067147
509		.000193 x	595.837395 =	.114997
509		.000072 x	595.837395 =	.042900
501		.000213 x	656.473521 =	.139829
522		.000286 x	489.113537 =	.139886
630		.020000 x	.549800 =	.010996
-----				
			T.E =	2.948558

3312	3312			
509		.000094 x	595.837395 =	.056009
-----				
			T.E =	.056009
3321A	3321A			
112		.030000 x	17.312112 =	.519363
509		.000072 x	595.837395 =	.042900
501		.000213 x	656.473521 =	.139829
614		.135000 x	11.382066 =	1.536579
509		.000193 x	595.837395 =	.114997
630		.020000 x	.549800 =	.010996
522		.000286 x	489.113537 =	.139886
-----				
			T.E =	2.504551
3321B	3321B			
112		.030000 x	17.312112 =	.519363
630		.020000 x	.549800 =	.010996
501		.000213 x	656.473521 =	.139829
509		.000193 x	595.837395 =	.114997
509		.000072 x	595.837395 =	.042900
522		.000286 x	489.113537 =	.139886
622		.135000 x	15.312201 =	2.067147
-----				
			T.E =	3.035119
3322	3322			
509		.000094 x	595.837395 =	.056009
-----				
			T.E =	.056009
3401	3401			
111		1.300000 x	15.741598 =	20.464077
521		.014286 x	349.347498 =	4.990778
509		.000361 x	595.837395 =	.215097
112		.900000 x	17.312112 =	15.580901
630		.100000 x	.549800 =	.054980
-----				
			T.E =	41.305834
3402A	3402A			
509		.001929 x	595.837395 =	1.149370
614		1.350000 x	11.382066 =	15.365789
-----				
			T.E =	16.515159
3402B	3402B			
622		1.350000 x	15.312201 =	20.671471
509		.001929 x	595.837395 =	1.149370
-----				
			T.E =	21.820842

3403	3403			
509		.000940 x	595.837395 =	.560087
			T.E =	.560087
4110	4110			
112		.008000 x	17.312112 =	.138497
671		1.200000 x	.984580 =	1.181496
526		.000100 x	599.986818 =	.059999
523		.000143 x	365.895178 =	.052323
			T.E =	1.432315
4110.1	4110.1			
112		.008000 x	17.312112 =	.138497
526		.000100 x	599.986818 =	.059999
671.1		1.200000 x	.656780 =	.788136
523		.000143 x	365.895178 =	.052323
			T.E =	1.038955
4120	4120			
321		.500000 x	.596000 =	.298000
525		.000067 x	256.385599 =	.017178
526		.000100 x	599.986818 =	.059999
523		.000143 x	365.895178 =	.052323
112		.006000 x	17.312112 =	.103873
			T.E =	.531372
4120.1	4120.1			
112		.006000 x	17.312112 =	.103873
523		.000143 x	365.895178 =	.052323
525		.000067 x	256.385599 =	.017178
526		.000100 x	599.986818 =	.059999
			T.E =	.233372
4131A	4131A			
321		1.000000 x	.596000 =	.596000
509		.000014 x	595.837395 =	.008342
112		.008000 x	17.312112 =	.138497
522		.000143 x	489.113537 =	.069943
509		.000028 x	595.837395 =	.016683
509		.000143 x	595.837395 =	.085205
616		.015000 x	11.382066 =	.170731
525		.000067 x	256.385599 =	.017178
526		.000143 x	599.986818 =	.085798
523		.000143 x	365.895178 =	.052323
504		.000143 x	824.456869 =	.117897
			T.E =	1.358597

4131A.1	4131A.1			
112		.008000 x	17.312112 =	.138497
509		.000014 x	595.837395 =	.008342
616		.015000 x	11.382066 =	.170731
525		.000067 x	256.385599 =	.017178
526		.000143 x	599.986818 =	.085798
523		.000143 x	365.895178 =	.052323
504		.000143 x	824.456869 =	.117897
509		.000028 x	595.837395 =	.016683
522		.000143 x	489.113537 =	.069943
509		.000143 x	595.837395 =	.085205
-----				
			T.E =	.762597
4131B	4131B			
321		1.000000 x	.596000 =	.596000
525		.000067 x	256.385599 =	.017178
526		.000143 x	599.986818 =	.085798
523		.000143 x	365.895178 =	.052323
509		.000143 x	595.837395 =	.085205
522		.000143 x	489.113537 =	.069943
624		.015000 x	15.312201 =	.229683
504		.000143 x	824.456869 =	.117897
509		.000014 x	595.837395 =	.008342
509		.000028 x	595.837395 =	.016683
112		.008000 x	17.312112 =	.138497
-----				
			T.E =	1.417549
4131B.1	4131B.1			
112		.008000 x	17.312112 =	.138497
525		.000067 x	256.385599 =	.017178
526		.000143 x	599.986818 =	.085798
523		.000143 x	365.895178 =	.052323
504		.000143 x	824.456869 =	.117897
509		.000014 x	595.837395 =	.008342
509		.000028 x	595.837395 =	.016683
509		.000143 x	595.837395 =	.085205
522		.000143 x	489.113537 =	.069943
624		.015000 x	15.312201 =	.229683
-----				
			T.E =	.821549
4132	4132			
509		.000009 x	595.837395 =	.005363
-----				
			T.E =	.005363

4141A	4141A			
112		.013000 x	17.312112 =	.225057
616		.012000 x	11.382066 =	.136585
615		.015000 x	11.382066 =	.170731
526		.000244 x	599.986818 =	.146397
523		.000143 x	365.895178 =	.052323
504		.000244 x	824.456869 =	.201167
509		.000244 x	595.837395 =	.145384
522		.000244 x	489.113537 =	.119344
672		1.500000 x	.689984 =	1.034976
509		.000038 x	595.837395 =	.022642
509		.000024 x	595.837395 =	.014300
671		1.200000 x	.984580 =	1.181496

-----  
 T.E = 3.450402

4141A.1	4141A.1			
112		.013000 x	17.312112 =	.225057
671.1		1.200000 x	.656780 =	.788136
616		.012000 x	11.382066 =	.136585
615		.015000 x	11.382066 =	.170731
526		.000244 x	599.986818 =	.146397
523		.000143 x	365.895178 =	.052323
504		.000244 x	824.456869 =	.201167
509		.000024 x	595.837395 =	.014300
509		.000038 x	595.837395 =	.022642
509		.000244 x	595.837395 =	.145384
522		.000244 x	489.113537 =	.119344
672.1		1.500000 x	.129744 =	.194616

-----  
 T.E = 2.216682

4141B	4141B			
112		.013000 x	17.312112 =	.225057
509		.000038 x	595.837395 =	.022642
509		.000244 x	595.837395 =	.145384
526		.000244 x	599.986818 =	.146397
523		.000143 x	365.895178 =	.052323
504		.000244 x	824.456869 =	.201167
509		.000024 x	595.837395 =	.014300
623		.015000 x	15.093056 =	.226396
522		.000244 x	489.113537 =	.119344
624		.012000 x	15.312201 =	.183746
672		1.500000 x	.689984 =	1.034976
671		1.200000 x	.984580 =	1.181496

-----  
 T.E = 3.553229

4141B.1	4141B.1			
112		.013000 x	17.312112 =	.225057
623		.015000 x	15.093056 =	.226396
526		.000244 x	599.986818 =	.146397
523		.000143 x	365.895178 =	.052323
504		.000244 x	824.456869 =	.201167
509		.000024 x	595.837395 =	.014300
509		.000038 x	595.837395 =	.022642
509		.000244 x	595.837395 =	.145384
522		.000244 x	489.113537 =	.119344
672.1		1.500000 x	.129744 =	.194616
671.1		1.200000 x	.656780 =	.788136
624		.012000 x	15.312201 =	.183746
			-----	
			T.E =	2.319509
4142	4142			
509		.000017 x	595.837395 =	.010129
			-----	
			T.E =	.010129
4211A	4211A			
672		25.000000 x	.689984 =	17.249600
501		.007024 x	656.473521 =	4.611070
616		.300000 x	11.382066 =	3.414620
615		.700000 x	11.382066 =	7.967446
526		.002857 x	599.986818 =	1.714162
509		.001429 x	595.837395 =	.851452
522		.003846 x	489.113537 =	1.881131
			-----	
			T.E =	37.689481
4211A.1	4211A.1			
672.1		25.000000 x	.129744 =	3.243600
522		.003846 x	489.113537 =	1.881131
509		.001429 x	595.837395 =	.851452
615		.700000 x	11.382066 =	7.967446
501		.007024 x	656.473521 =	4.611070
616		.300000 x	11.382066 =	3.414620
526		.002857 x	599.986818 =	1.714162
			-----	
			T.E =	23.683481
4211B	4211B			
623		.700000 x	15.093056 =	10.565139
522		.003846 x	489.113537 =	1.881131
501		.007024 x	656.473521 =	4.611070
624		.300000 x	15.312201 =	4.593660
526		.002857 x	599.986818 =	1.714162
509		.001429 x	595.837395 =	.851452
672		25.000000 x	.689984 =	17.249600
			-----	
			T.E =	41.466214

4211B.1	4211B.1			
623		.700000 x	15.093056 =	10.565139
501		.007024 x	656.473521 =	4.611070
526		.002857 x	599.986818 =	1.714162
509		.001429 x	595.837395 =	.851452
522		.003846 x	489.113537 =	1.881131
672.1		25.000000 x	.129744 =	3.243600
624		.300000 x	15.312201 =	4.593660
			T.E =	27.460214
4212	4212			
509		.000614 x	595.837395 =	.365844
			T.E =	.365844
4221A	4221A			
672		37.000000 x	.689984 =	25.529408
615		.600000 x	11.382066 =	6.829240
501		.008226 x	656.473521 =	5.400151
616		.400000 x	11.382066 =	4.552826
522		.004348 x	489.113537 =	2.126666
526		.004000 x	599.986818 =	2.399947
509		.001429 x	595.837395 =	.851452
			T.E =	47.689690
4221A.1	4221A.1			
672.1		37.000000 x	.129744 =	4.800528
501		.008226 x	656.473521 =	5.400151
616		.400000 x	11.382066 =	4.552826
615		.600000 x	11.382066 =	6.829240
526		.004000 x	599.986818 =	2.399947
522		.004348 x	489.113537 =	2.126666
509		.001429 x	595.837395 =	.851452
			T.E =	26.960810
4221B	4221B			
623		.600000 x	15.093056 =	9.055834
501		.008226 x	656.473521 =	5.400151
526		.004000 x	599.986818 =	2.399947
509		.001429 x	595.837395 =	.851452
624		.400000 x	15.312201 =	6.124880
522		.004348 x	489.113537 =	2.126666
672		37.000000 x	.689984 =	25.529408
			T.E =	51.488338

4221B.1	4221B.1			
623		.600000 x	15.093056 =	9.055834
501		.008226 x	656.473521 =	5.400151
526		.004000 x	599.986818 =	2.399947
672.1		37.000000 x	.129744 =	4.800528
522		.004348 x	489.113537 =	2.126666
509		.001429 x	595.837395 =	.851452
624		.400000 x	15.312201 =	6.124880
			T.E =	30.759458
4222	4222			
509		.000614 x	595.837395 =	.365844
			T.E =	.365844
4231A	4231A			
112		.005000 x	17.312112 =	.086561
616		.006000 x	11.382066 =	.068292
615		.025000 x	11.382066 =	.284552
526		.000222 x	599.986818 =	.133197
523		.000143 x	365.895178 =	.052323
509		.000044 x	595.837395 =	.026217
509		.000036 x	595.837395 =	.021450
509		.000357 x	595.837395 =	.212714
522		.000357 x	489.113537 =	.174614
672		2.500000 x	.689984 =	1.724960
112		.030000 x	17.312112 =	.519363
			T.E =	3.304243
4231A.1	4231A.1			
112		.005000 x	17.312112 =	.086561
509		.000357 x	595.837395 =	.212714
616		.006000 x	11.382066 =	.068292
615		.025000 x	11.382066 =	.284552
526		.000222 x	599.986818 =	.133197
523		.000143 x	365.895178 =	.052323
509		.000036 x	595.837395 =	.021450
522		.000357 x	489.113537 =	.174614
672.1		2.500000 x	.129744 =	.324360
112		.030000 x	17.312112 =	.519363
509		.000044 x	595.837395 =	.026217
			T.E =	1.903643

4231B	4231B			
112		.005000 x	17.312112 =	.086561
623		.025000 x	15.093056 =	.377326
672		2.500000 x	.689984 =	1.724960
526		.000222 x	599.986818 =	.133197
523		.000143 x	365.895178 =	.052323
509		.000357 x	595.837395 =	.212714
509		.000036 x	595.837395 =	.021450
509		.000044 x	595.837395 =	.026217
522		.000357 x	489.113537 =	.174614
624		.006000 x	15.312201 =	.091873
112		.030000 x	17.312112 =	.519363
-----				
			T.E =	3.420598
4231B.1	4231B.1			
112		.005000 x	17.312112 =	.086561
509		.000044 x	595.837395 =	.026217
526		.000222 x	599.986818 =	.133197
523		.000143 x	365.895178 =	.052323
509		.000357 x	595.837395 =	.212714
522		.000357 x	489.113537 =	.174614
672.1		2.500000 x	.129744 =	.324360
624		.006000 x	15.312201 =	.091873
509		.000036 x	595.837395 =	.021450
623		.025000 x	15.093056 =	.377326
112		.030000 x	17.312112 =	.519363
-----				
			T.E =	2.019998
4232	4232			
509		.000024 x	595.837395 =	.014300
-----				
			T.E =	.014300
4321A	4321A			
521		.000128 x	349.347498 =	.044716
523		.000143 x	365.895178 =	.052323
4312		.071000 x	1.790905 =	.127154
4311A		.071000 x	69.050420 =	4.902580
528		.000128 x	876.155462 =	.112148
509		.000101 x	595.837395 =	.060180
522		.000128 x	489.113537 =	.062607
-----				
			T.E =	5.361708

4321A.1	4321A.1			
521		.000128 x	349.347498 =	.044716
4312		.071000 x	1.790905 =	.127154
4311A.1		.071000 x	21.370420 =	1.517300
528		.000128 x	876.155462 =	.112148
522		.000128 x	489.113537 =	.062607
523		.000143 x	365.895178 =	.052323
509		.000101 x	595.837395 =	.060180
				-----
			T.E =	1.976428
4321B	4321B			
521		.000128 x	349.347498 =	.044716
522		.000128 x	489.113537 =	.062607
4312		.071000 x	1.790905 =	.127154
4311B		.071000 x	71.209513 =	5.055875
528		.000128 x	876.155462 =	.112148
523		.000143 x	365.895178 =	.052323
509		.000101 x	595.837395 =	.060180
				-----
			T.E =	5.515003
4321B.1	4321B.1			
521		.000128 x	349.347498 =	.044716
4312		.071000 x	1.790905 =	.127154
4311B.1		.071000 x	23.529513 =	1.670595
528		.000128 x	876.155462 =	.112148
523		.000143 x	365.895178 =	.052323
509		.000101 x	595.837395 =	.060180
522		.000128 x	489.113537 =	.062607
				-----
			T.E =	2.129723
4322	4322			
509		.000049 x	595.837395 =	.029196
				-----
			T.E =	.029196
4421A	4421A			
521		.000128 x	349.347498 =	.044716
528		.000128 x	876.155462 =	.112148
4411A		.071000 x	69.050420 =	4.902580
4312		.071000 x	1.790905 =	.127154
523		.000143 x	365.895178 =	.052323
509		.000101 x	595.837395 =	.060180
522		.000128 x	489.113537 =	.062607
				-----
			T.E =	5.361708

4421A.1	4421A.1			
521		.000128 x	349.347498 =	.044716
509		.000101 x	595.837395 =	.060180
522		.000128 x	489.113537 =	.062607
4412		.071000 x	1.790905 =	.127154
4411A.1		.071000 x	21.370420 =	1.517300
528		.000128 x	876.155462 =	.112148
523		.000143 x	365.895178 =	.052323
-----				
			T.E =	1.976428
4421B	4421B			
521		.000128 x	349.347498 =	.044716
522		.000128 x	489.113537 =	.062607
509		.000101 x	595.837395 =	.060180
523		.000143 x	365.895178 =	.052323
4411B		.071000 x	71.209513 =	5.055875
4412		.071000 x	1.790905 =	.127154
528		.000128 x	876.155462 =	.112148
-----				
			T.E =	5.515003
4421B.1	4421B.1			
521		.000128 x	349.347498 =	.044716
522		.000128 x	489.113537 =	.062607
509		.000101 x	595.837395 =	.060180
4412		.071000 x	1.790905 =	.127154
4411B.1		.071000 x	23.529513 =	1.670595
528		.000128 x	876.155462 =	.112148
523		.000143 x	365.895178 =	.052323
-----				
			T.E =	2.129723
4422	4422			
509		.000049 x	595.837395 =	.029196
-----				
			T.E =	.029196
4521A	4521A			
521		.000128 x	349.347498 =	.044716
4512		.071000 x	1.790905 =	.127154
4511A		.071000 x	75.371782 =	5.351397
528		.000128 x	876.155462 =	.112148
522		.000128 x	489.113537 =	.062607
523		.000143 x	365.895178 =	.052323
509		.000101 x	595.837395 =	.060180
-----				
			T.E =	5.810524

4521A.1	4521A.1			
521		.000128 x	349.347498 =	.044716
523		.000143 x	365.895178 =	.052323
509		.000101 x	595.837395 =	.060180
4511A.1		.071000 x	21.731782 =	1.542957
4512		.071000 x	1.790905 =	.127154
528		.000128 x	876.155462 =	.112148
522		.000128 x	489.113537 =	.062607
			T.E =	2.002084
4521B	4521B			
521		.000128 x	349.347498 =	.044716
4512		.071000 x	1.790905 =	.127154
4511B		.071000 x	77.923889 =	5.532596
528		.000128 x	876.155462 =	.112148
523		.000143 x	365.895178 =	.052323
509		.000101 x	595.837395 =	.060180
522		.000128 x	489.113537 =	.062607
			T.E =	5.991724
4521B.1	4521B.1			
521		.000128 x	349.347498 =	.044716
509		.000101 x	595.837395 =	.060180
523		.000143 x	365.895178 =	.052323
4511B.1		.071000 x	24.283889 =	1.724156
4512		.071000 x	1.790905 =	.127154
528		.000128 x	876.155462 =	.112148
522		.000128 x	489.113537 =	.062607
			T.E =	2.183284
4522	4522			
509		.000049 x	595.837395 =	.029196
			T.E =	.029196
4611.1	4611.1			
326		45.000000 x	1.310000 =	58.950000
522		.000667 x	489.113537 =	.326239
623		.033000 x	15.093056 =	.498071
113		.100000 x	20.419486 =	2.041949
529		.002857 x	765.951336 =	2.188323
4120.1		1.000000 x	.233372 =	.233372
525		.000286 x	256.385599 =	.073326
509		.000046 x	595.837395 =	.027409
617		.013000 x	5.795712 =	.075344
			T.E =	64.414032

4611A	4611A			
321		3.000000 x	.596000 =	1.788000
326		45.000000 x	1.310000 =	58.950000
4120		1.000000 x	.531372 =	.531372
529		.002857 x	765.951336 =	2.188323
525		.000286 x	256.385599 =	.073326
509		.000046 x	595.837395 =	.027409
522		.000667 x	489.113537 =	.326239
623		.033000 x	15.093056 =	.498071
617		.013000 x	5.795712 =	.075344
113		.100000 x	20.419486 =	2.041949
			T.E =	66.500032
4612	4612			
509		.000040 x	595.837395 =	.023833
			T.E =	.023833
4710A	4710A			
111		1.900000 x	15.741598 =	29.909036
509		.005305 x	595.837395 =	3.160917
613		1.000000 x	6.450458 =	6.450458
509		.000361 x	595.837395 =	.215097
112		2.400000 x	17.312112 =	41.549069
630		.200000 x	.549800 =	.109960
112		1.200000 x	17.312112 =	20.774534
			T.E =	102.169072
4710A.1	4710A.1			
111		1.900000 x	15.741598 =	29.909036
614		1.000000 x	11.382066 =	11.382066
509		.000361 x	595.837395 =	.215097
630		.200000 x	.549800 =	.109960
112		2.400000 x	17.312112 =	41.549069
509		.005305 x	595.837395 =	3.160917
112		1.200000 x	17.312112 =	20.774534
			T.E =	107.100680
4710B	4710B			
111		1.900000 x	15.741598 =	29.909036
509		.000361 x	595.837395 =	.215097
509		.005305 x	595.837395 =	3.160917
630		.200000 x	.549800 =	.109960
622		1.000000 x	15.312201 =	15.312201
112		2.400000 x	17.312112 =	41.549069
112		1.200000 x	17.312112 =	20.774534
			T.E =	111.030815

4720A	4720A			
111		1.900000 x	15.741598 =	29.909036
4522		140.000000 x	.029196 =	4.087440
4512		1.000000 x	1.790905 =	1.790905
671		20.000000 x	.984580 =	19.691600
112		2.400000 x	17.312112 =	41.549069
112		2.000000 x	17.312112 =	34.624224
4511B		1.000000 x	77.923889 =	77.923889
111		1.000000 x	15.741598 =	15.741598
-----				
			T.E =	225.317761
4720A.1	4720A.1			
111		1.900000 x	15.741598 =	29.909036
111		1.000000 x	15.741598 =	15.741598
4522		140.000000 x	.029196 =	4.087440
4512		1.000000 x	1.790905 =	1.790905
4511B.1		1.000000 x	24.283889 =	24.283889
671.1		20.000000 x	.656780 =	13.135600
112		2.000000 x	17.312112 =	34.624224
112		2.400000 x	17.312112 =	41.549069
-----				
			T.E =	165.121761
4800	4800			
325		1.000000 x	2.780000 =	2.780000
112		.010000 x	17.312112 =	.173121
-----				
			T.E =	2.953121